•1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources** Department Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-144 Revised June 6, 2013

For temporary pits, below-grade tanks, and multi-well fluid management pits, submit to the appropriate NMOCD District Office. For permanent pits submit to the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD District Office.

Pit, Below-Grade Tank, or									
12680 Proposed Alternative Method Permit or Closure Plan Application CEIVED									
Type of action: Below grade tank registration									
45-09/54 Permit of a pit or proposed alternative method Closure of a pit, below-grade tank, or proposed alternative method FEB 1 8 2015									
Modification to an existing permit/or registration									
Closure plan only submitted for an existing permitted or non-permitted pit, below-grade tank, or proposed alternative method									
Instructions: Please submit one application (Form C-144) per individual pit, below-grade tank or alternative request									
Please be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the									
environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.									
Operator: BP America Production CompanyOGRID#:778									
Address:200 Energy Court, Farmington, NM 87401									
Facility or well name:Heath Gas Com C 1									
API Number:30045 09154 OCD Permit Number:7678									
U/L or Qtr/QtrKSection30Township30NRange9WCounty:San Juan									
Center of Proposed Design: Latitude36.780541 Longitude107.824887 NAD: ☐1927 ⊠ 1983									
Surface Owner: Federal State Private Tribal Trust or Indian Allotment									
2.									
Pit: Subsection F, G or J of 19.15.17.11 NMAC									
Temporary: Drilling Workover									
☐ Permanent ☐ Emergency ☐ Cavitation ☐ P&A ☐ Multi-Well Fluid Management Low Chloride Drilling Fluid ☐ yes ☐ no									
☐ Lined ☐ Unlined Liner type: Thicknessmil ☐ LLDPE ☐ HDPE ☐ PVC ☐ Other									
Liner Seams: Welded Factory Other Volume: bbl Dimensions: L x W x D									
3. Below-grade tank: Subsection I of 19.15.17.11 NMAC Tank B									
Volume:45.0bbl · Type of fluid:Produced water									
Tank Construction material: Steel									
☐ Secondary containment with leak detection ☐ Visible sidewalls, liner, 6-inch lift and automatic overflow shut-off									
☐ Visible sidewalls and liner ☐ Visible sidewalls only ☒ Other _Single walled/double bottomed, sidewalls not visible									
Liner type: Thicknessmil									
4.									
Alternative Method:									

Submittal of an exception request is required. Exceptions must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.

s. *Fencing: Subsection D of 19.15.17.11 NMAC (Applies to permanent pits, temporary pits, and below-grade tanks)	
Chain link, six feet in height, two strands of barbed wire at top (Required if located within 1000 feet of a permanent residence, school,	hospital,
institution or church) Four foot height, four strands of barbed wire evenly spaced between one and four feet	
Alternate. Please specify	
6.	
Netting: Subsection E of 19.15.17.11 NMAC (Applies to permanent pits and permanent open top tanks)	
☐ Screen ☐ Netting ☐ Other	
Monthly inspections (If netting or screening is not physically feasible)	
7.	
Signs: Subsection C of 19.15.17.11 NMAC ☐ 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers	
Signed in compliance with 19.15.16.8 NMAC	
8. Variances and Exceptions:	
Justifications and/or demonstrations of equivalency are required. Please refer to 19.15.17 NMAC for guidance. Please check a box if one or more of the following is requested, if not leave blank:	
Variance(s): Requests must be submitted to the appropriate division district for consideration of approval.	
Exception(s): Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.	
9.	
Siting Criteria (regarding permitting): 19.15.17.10 NMAC Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of acceptance of the compliance of the complianc	ptable source
material are provided below. Siting criteria does not apply to drying pads or above-grade tanks.	
General siting	
	_
- WATERS database search; USGS; Data obtained from nearby wells	Yes No
Ground water is less than 50 feet below the bottom of a Temporary pit, permanent pit, or Multi-Well Fluid Management pit. NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	Yes No
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. (Does not apply to below grade tanks)	☐ Yes ☐ No
- Written confirmation or verification from the municipality; Written approval obtained from the municipality	
Within the area overlying a subsurface mine. (Does not apply to below grade tanks) - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☐ No
Within an unstable area. (Does not apply to below grade tanks)	☐ Yes ☐ No
 Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map 	
Within a 100-year floodplain. (Does not apply to below grade tanks) - FEMA map	Yes No
Below Grade Tanks	
Within 100 feet of a continuously flowing watercourse, significant watercourse, lake bed, sinkhole, wetland or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 200 horizontal feet of a spring or a fresh water well used for public or livestock consumption;	☐ Yes ☐ No
- NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	
Temporary Pit using Low Chloride Drilling Fluid (maximum chloride content 15,000 mg/liter)	
Within 100 feet of a continuously flowing watercourse, or any other significant watercourse or within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). (Applies to low chloride temporary pits.) - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No

Within 300 feet from a occupied permanent residence, school, hospital, institution, or church in existence at the time of initial application.	Yes No
- Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	
Within 200 horizontal feet of a spring or a private, domestic fresh water well used by less than five households for domestic or stock watering purposes, or 300feet of any other fresh water well or spring, in existence at the time of the initial application. NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	Yes No
Within 100 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Temporary Pit Non-low chloride drilling fluid	
Within 300 feet of a continuously flowing watercourse, or any other significant watercourse, or within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	Yes No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	Yes No
Within 500 horizontal feet of a spring or a private, domestic fresh water well used by less than five households for domestic or stock watering purposes, or 1000 feet of any other fresh water well or spring, in the existence at the time of the initial application; - NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 300 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Permanent Pit or Multi-Well Fluid Management Pit	
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	Yes No
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	Yes No
Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of	
initial application NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 500 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	Yes No
Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19.15.17.9 N Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the docattached.	
Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9 Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19. and 19.15.17.13 NMAC	
Previously Approved Design (attach copy of design) API Number: or Permit Number:	
Multi-Well Fluid Management Pit Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the docattached.	cuments are .
 □ Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC □ Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC □ A List of wells with approved application for permit to drill associated with the pit. □ Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19 and 19.15.17.13 NMAC □ Hydrogeologic Data - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC 	15.17.9 NMAC
☐ Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC ☐ Previously Approved Design (attach copy of design) API Number:	
Treviously Approved Design (attach copy of design) Att I runned.	

Permanent Pits Permit Application Checklist: Subsection B of 19.15.17.9 NMAC						
Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the attached.	documents are					
Hydrogeologic Report - based upon the requirements of Paragraph (1) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Climatological Factors Assessment Certified Engineering Design Plans - based upon the appropriate requirements of 19.15.17.11 NMAC Dike Protection and Structural Integrity Design - based upon the appropriate requirements of 19.15.17.11 NMAC Leak Detection Design - based upon the appropriate requirements of 19.15.17.11 NMAC						
 □ Liner Specifications and Compatibility Assessment - based upon the appropriate requirements of 19.15.17.11 NMAC □ Quality Control/Quality Assurance Construction and Installation Plan □ Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC □ Freeboard and Overtopping Prevention Plan - based upon the appropriate requirements of 19.15.17.11 NMAC □ Nuisance or Hazardous Odors, including H₂S, Prevention Plan □ Emergency Response Plan □ Oil Field Waste Stream Characterization 						
Monitoring and Inspection Plan						
☐ Erosion Control Plan ☐ Closure Plan - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC	,					
Proposed Closure: 19.15.17.13 NMAC Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan.						
Type: Drilling Workover Emergency Cavitation P&A Permanent Pit Below-grade Tank Multi-well Fl	uid Management Pit					
Proposed Closure Method: Waste Excavation and Removal Waste Removal (Closed-loop systems only) On-site Closure Method (Only for temporary pits and closed-loop systems) In-place Burial On-site Trench Burial Alternative Closure Method						
Waste Excavation and Removal Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be a closure plan. Please indicate, by a check mark in the box, that the documents are attached. Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.13 NMAC Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings) Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC Site Reclamation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC						
Siting Criteria (regarding on-site closure methods only): 19.15.17.10 NMAC Instructions: Each siting criteria requires a demonstration of compliance in the closure plan. Recommendations of acceptable sour provided below. Requests regarding changes to certain siting criteria require justifications and/or demonstrations of equivalency. P 19.15.17.10 NMAC for guidance.						
Ground water is less than 25 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	Yes No .					
Ground water is between 25-50 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA					
Ground water is more than 100 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells \[\begin{array}{c} \text{Yes} \bigcap \text{N} \\ \end{array} \] \[\begin{array}{c} \text{Yes} \bigcap \text{N} \\ \end{array} \]						
Within 100 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site						
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image						
Within 300 horizontal feet of a private, domestic fresh water well or spring used for domestic or stock watering purposes, in existence at the time of initial application. - NM Office of the State Engineer - iWATERS database; Visual inspection (certification) of the proposed site						
Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ☐ No					
Within 300 feet of a wetland. US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No					
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance						

adopted pursuant to NMSA 1978, Section 3-27-3, as amended. • Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ☐ No										
Within the area overlying a subsurface mine. - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division											
Within an unstable area. - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map											
Within a 100-year floodplain.	Yes No										
- FEMA map	Yes No										
On-Site Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be attached to the closure plan. Please indicate, by a check mark in the box, that the documents are attached. Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Proof of Surface Owner Notice - based upon the appropriate requirements of Subsection E of 19.15.17.13 NMAC Construction/Design Plan of Burial Trench (if applicable) based upon the appropriate requirements of Subsection K of 19.15.17.11 NMAC Construction/Design Plan of Temporary Pit (for in-place burial of a drying pad) - based upon the appropriate requirements of 19.15.17.13 NMAC Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of 19.15.17.13 NMAC Waste Material Sampling Plan - based upon the appropriate requirements of 19.15.17.13 NMAC Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings or in case on-site closure standards cannot be achieved) Soil Cover Design - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC Site Reclamation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC											
Operator Application Certification:											
I hereby certify that the information submitted with this application is true, accurate and complete to the best of my knowledge and beli	ef.										
Name (Print): Title:											
Signature: Date:											
e-mail address: Telephone:											
OCD Approval: Permit Application (including closure plan) Closure Plan (enly) OCD Conditions (see attachment) OCD Representative Signature: Approval Date: 3/19/	9015										
19.											
Closure Report (required within 60 days of closure completion): 19.15.17.13 NMAC Instructions: Operators are required to obtain an approved closure plan prior to implementing any closure activities and submitting The closure report is required to be submitted to the division within 60 days of the completion of the closure activities. Please do not section of the form until an approved closure plan has been obtained and the closure activities have been completed.											
☐ Closure Completion Date:8/19/2010											
20. Closure Method: Waste Excavation and Removal ☐ On-Site Closure Method ☐ Alternative Closure Method ☐ Waste Removal (Closed-lo ☐ If different from approved plan, please explain.	op systems only)										

22. • Operator Closure Certification:	•
I hereby certify that the information and attachments submitted with this closure belief. I also certify that the closure complies with all applicable closure requires	
Name (Print):Jeff Peace	Title: Field Environmental Coordinator
Signature: Joff Reserve	Date:February 17, 2015
e-mail address:peace.jeffrey@bp.com	Telephone:(505) 326-9479

BP AMERICA PRODUCTION COMPANY

SAN JUAN BASIN, NORTHWEST NEW MEXICO

BELOW-GRADE TANK CLOSURE PLAN

Heath Gas Com C 1 BGT Tank B (45 bbl) API No. 3004509154 Unit Letter K, Section 30, T30N, R9W

This plan will address the standard protocols and procedures for closure of below-grade tanks (BGTs) on BP America Production Company (BP) well sites. As stipulated in Paragraph A of 19.15.17.13 NMAC, BP shall close a BGT within the time periods provided in 19.15.17.13 NMAC, or by an earlier date that the New Mexico Oil Conservation Division (NMOCD) requires because of imminent danger to fresh water, public health, safety or the environment. If deviations from this plan are necessary, any specific changes will be included on form C-144 and approved by the NMOCD. BP shall close an existing BGT that does not meet the requirements of Paragraphs (1) through (4) of Subsection I of 19.15.17.11 NMAC or is not included in Paragraph (5) of Subsection I of 19.15.17.11 NMAC within five years after June 16, 2008, if not retrofit with a BGT that complies with the BP NMOCD approved BGT design attached to the BP Design and Construction Plan. BP shall close an existing BGT that does not meet the requirements of Paragraphs (1) through (4) of Subsection I of 19.15.17.11 NMAC, if not previously retrofitted to comply with the BP NMOCD approve BGT Design attached to the BP Design and Construction Plan, prior to any sale or change in operator pursuant to 19.15.9.9 NMAC. BP shall close the permitted BGT within 60 days of cessation of the BGTs operation or as required by the transitional provisions of Subsection B, D, or E of 19.15.17.17 NMAC.

General Closure Plan

- 1. BP shall notify the surface owner by certified mail that it plans to close a BGT. Evidence of mailing of the notice to the address of the surface owner shown in the county tax records demonstrates compliance with this requirement.
 - No notice was made due to misunderstanding of the BGT notice requirements at that time.
- 2. BP shall notify the division District III office verbally or by other means at least 72 hours, but not more than one (1) week, prior to any closure operation. The notice shall include the operator's name, and the location to be closed by unit letter, section, township and range. If the BGT closure is associated with a particular well, then the notice shall also include the well's name, number and API number.
 - No notice was made due to misunderstanding of the BGT notice requirements at that time.
- 3. BP shall remove liquids and sludge from the BGT prior to implementing a closure method and dispose of the liquids and sludge in a NMOCD's division-approved facility. The facilities to be used are:
 - a. BP Crouch Mesa Landfarm, Permit NM-02-003 (Solids)
 - b. JFJ Landfarm, Permit NM-01-010(B) (Solids and Sludge)
 - c. Basin Disposal, Permit NM-01-0005 (Liquids)

- d. Envirotech Inc Soil Remediation Facility, Permit NM-01-0011 (Solids and Sludge)
- e. BP Operated E.E. Elliott SWD #1, API 30-045-27799 (Liquids)
- f. BP Operated 13 GCU SWD #1, API 30-045-28601 (Liquids)
- g. BP Operated GCU 259 SWD, API 30-045-20006 (Liquids)
- h. BP Operated GCU 306 SWD, API 30-045-24286 (Liquids)
- i. BP Operated GCU 307 SWD, API 30-045-24248 (Liquids)
- j. BP Operated GCU 328 SWD, API 30-045-24735 (Liquids)
- k. BP Operated Pritchard SWD #1, API 30-045-28351 (Liquids)

All liquids and sludge in the BGT were removed and sent to one of the above NMOCD approved facilities for disposal.

4. BP shall remove the BGT and dispose of it in a NMOCD approved facility or recycle, reuse, or reclaim it in a manner that the NMOCD approves. If a liner is present and must be disposed of it will be cleaned by scraping any soils or other attached materials on the liner to a de minimus amount and disposed at a permitted solid waste facility, pursuant to Subparagraph (m) of Paragraph (1) of Subsection C of 19.15.35.8 NMAC. Documentation as to the final disposition of the removed BGT will be provided in the final closure report.

The BGT was transported to a storage area for sale and re-use.

5. BP shall remove any on-site equipment associated with a BGT unless the equipment is required for well production.

All equipment associated with the BGT has been removed.

6. BP shall test the soils beneath the BGT to determine whether a release has occurred. BP shall collect at a minimum: a five (5) point composite sample and individual grab samples from any area that is wet, discolored or showing other evidence of a release and analyze for BTEX, TPH and chlorides. The testing methods for those constituents are as follows;

Constituents	Testing Method	Release Verification	Sample
	45 bbl BGT, Tank B	(mg/Kg)	results
Benzene	US EPA Method SW-846 8021B or 8260B	0.2	ND
Total BTEX	US EPA Method SW-846 8021B or 8260B	50.	ND
TPH	US EPA Method SW-846 418.1	100	25
Chlorides	US EPA Method 300.0 or 4500B	250 or background	ND

Notes: mg/Kg = milligram per kilogram, BTEX = benzene, toluene, ethylbenzene, and total xylenes, TPH = total petroleum hydrocarbons. Other EPA methods that the division approves may be applied to all constituents listed. Chloride closure standards will be determined by which ever concentration level is greatest.

Soil under the BGT was sampled and TPH, BTEX and chloride levels were below the stated limits. Sampling data is attached.

- 7. BP shall notify the division District III office of its results on form C-141. C-141 is attached.
- If it is determined that a release has occurred, then BP will comply with 19.15.30 NMAC and 19.15.29 NMAC, as appropriate.
 Sampling results indicate no release occurred.
- 9. If the sampling demonstrates that a release has not occurred or that any release does not exceed the concentrations specified above, then BP shall backfill the excavation, with compacted, non-waste containing, earthen material; construct a division-prescribed soil cover, re-contour and re-vegetate the location. The location will be reclaimed if it is not with in the active process area

The area under the BGT was backfilled with clean soil and has been reclaimed since the well was plugged and abandoned.

10. BP shall reclaim the BGT location and all areas associated with the BGT including associated access roads to a safe and stable condition that blends with the surrounding undisturbed area. BP shall substantially restore the impacted surface area to the condition that existed prior to oil and gas operations by placement of the soil cover as provided in Subsection H of 19.15.17.13 NMAC, re-contour the location and associated areas to a contour that approximates the original contour and blends with the surrounding topography and re-vegetate according to Subsection I of 19.15.17.13 NMAC.

The area over the BGT has been reclaimed since the well was plugged and abandoned.

11. The soil cover for closures where the BGT has been removed or remediated to the NMOCD's satisfaction shall consist of the background thickness of topsoil or one foot of suitable material to establish vegetation at the site, whichever is greater. The soil cover will be constructed to the site's existing grade and all practicable efforts will be made to prevent ponding of water and erosion of the cover material.

The area over the BGT has been reclaimed since the well was plugged and abandoned.

12. BP shall seed the disturbed area the first growing season after closure of the BGT. Seeding will be accomplished by drilling on the contour whenever practical or by other division-approved methods. Vegetative cover will be, at a minimum, 70% of the native perennial vegetative cover (un-impacted by overgrazing, fire or other intrusion damaging to native vegetation), consisting of at least three native plant species, including at least one grass, but not including noxious weeds, and maintenance of that cover through two successive growing seasons. During the two growing seasons that prove viability, there shall be no artificial irrigation of the vegetation.

The area over the BGT has been reclaimed since the well was plugged and abandoned.

13. BP shall seed, plant and re-seed pursuant to Paragraph (3) of Subsection I of 19.15.17.13 NMAC, until the location successfully achieves the required vegetative cover

BP has seeded the area as part of final reclamation since the well was plugged and abandoned.

14. Pursuant to Paragraph (5) of Subsection I of 19.15.17.13 NMAC, BP shall notify the NMOCD when it has seeded or planted and when it successfully achieves revegetation.

BP will notify NMOCD when re-vegetation is successful.

- 15. Within 60 days of closure completion, BP shall submit a closure report on NMOCD's form C-144, and will include the following;
 - a. proof of closure notification (surface owner and NMOCD)
 - b. sampling analytical reports; information required by 19.15.17 NMAC;
 - c. disposal facility name and permit number
 - d. details on back-filling, capping, covering, and where applicable re-vegetation application rates and seeding techniques and
 - e. site reclamation, photo documentation.

 Closure report on C-144 form is included.
- 16. BP shall certify that all information in the report and attachments is accurate, truthful, and compliant with all applicable closure requirements and conditions specified in the approved closure plan.

Certification section of C-144 has been completed.

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.


Release Notification and Corrective Action											
						OPERATOR Initial Report S Fin					Final Report
Name of Co						Contact: Jef	f Peace				
Address: 200 Energy Court, Farmington, NM 87401						Telephone 1	No.: 505-326-94	79			
Facility Nar	ne: Heath	Gas Com C	1			Facility Typ	e: Natural gas v	vell	1 21-24		
Surface Ow	ner: Feder	al		Mineral C)wner: I	Federal		API	No. 30045	09154	
				LOCA	ATION	OF REI	LEASE				
Unit Letter K	Section 30	Township 30N	Range 9W	Feet from the 1,850	North/ South	South Line	Feet from the 600	East/West Lin West	e County	: San Jua	n .
		Latit	ude 36.	.780541		Longitud	e107.824887_		_		
				NAT	URE	OF RELI	EASE				
Type of Relea	ase: none			··			Release: N/A	Volun	e Recovered	i: N/A	
		w grade tank -	45 bbl, Ta	ank B		Date and H	lour of Occurrenc		nd Hour of		y:
Was Immedia	ate Notice (Yes \Box	No 🛭 Not Re	eauired	If YES, To	Whom?				
By Whom?						Date and H	lour			· -	
Was a Watercourse Reached?						<u> </u>	lume Impacting t	he Watercourse			*
☐ Yes ☒ No											
If a Watercou	rse was Im	pacted, Descri	ibe Fully.*		-						
Describe Cau	se of Probl	em and Remed	dial Action	Taken.* Sampli	ng of the	soil beneath	the BGT was dor	ne during remo	al to ensure	no soil ii	mpacts from
the BGT. So	il analysis r	esulted in TPI	H, BTEX a	and chloride belov	w standa	rds. Analysi	s results are attac	hed.			
							nderneath the BG		The area u	nder the I	3GT was
backfilled and	d compacted	d and has beer	n reclaime	d and seeded sinc	e the we	ll was plugge	d and abandoned.	•			
							knowledge and u				
							nd perform correct				
							arked as "Final Re				
				•			on that pose a thre	-			
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.											
OIL CONSERVATION DIVISION											
()	all V	0 -					OIL COIN	<u>JEIC VILLIC</u>	11 101 110	1011	
Signature: Signature:											
Printed Name	: Jeff Peace	9			F	Approved by	Environmental Sp	pecialist:			
Title: Field E	nvironment	tal Coordinato	r			Approval Dat	e:	Expirati	on Date:		
E-mail Address: peace.jeffrey@bp.com						Conditions of Approval: Attached					

Phone: 505-326-9479

Date: February 17, 2015

* Attach Additional Sheets If Necessary

CLIENT: BP	BLAGG ENGIN P.O. BOX 87, BLOOF (505) 632	MFIELD, NM 87413		API#: 3004509154
FIELD REPORT:	BGT CONFIRMATION TEMP. PIT CLO	OSURE / RELEASE INVESTIGATION		PAGE No:1 of1
SITE INFORMATION				DATE STARTED: 07/29/10
QUAD/UNIT: K SEC: 30 TW	P: 30N RNG: 9W PM: NM	CNTY: SJ ST: NM		DATE FINISHED:
	600'W NE/SW LEASE TYPE: PROD. FORMATION: MV CO	FEDERAL STATE / FEE / INDICATE OF THE PROPERTY	IDIAN	ENVIRONMENTAL SPECIALIST: JCB
REFERENCE POINT			107 825	213 GL ELEV.: 6,075'
1) 45 BGT (SW/DB)		41 X 107.824887		ARING FROM WH.: 138', \$44E
	GPS COORD.:		DISTANCE/BE/	ARING FROM W.H.:
3)	GPS COORD:			ARING FROM W.H.: ARING FROM W.H.:
<i>'</i>	GPS COORD.:			ARING FROM W.H.:
LAB INFORMATION:	CHAIN OF CUSTODY RECO	PRD(S): HALL		OVM READING
1) SAMPLE ID: 45 BGT 5-pt. @		SAMPLE TIME: 1230 LAB ANALYS	sis: 418.1	
2) SAMPLE ID:				, ,
3) SAMPLE ID:				
5) SAMPLE ID:				
SOIL DESCRIPTION	SOIL TYPE: SAND / SILTY SA	ND SILT / SILTY CLAY / CLAY / G	RAVEL / OTI	HER
SOIL COLOR: DARK YELL				D: YES NO EXPLANATION -
COHESION (ALL OTHERS): NON COHESIVE SLIGHT				
CONSISTENCY (NON COHESIVE SOILS): L PLASTICITY (CLAYS): NON PLASTIC / SLIGHTLY PLASTIC		HC ODOR DETECTED: YES	FNOI EVE	LANATION
DENSITY (COHESIVE CLAYS & SILTS): SOF		——————————————————————————————————————		LANATION
MOISTURE: DRY/SLIGHTLY MOIST / MOIST / W		SAMPLE TYPE: GRAB COMP	OSITE - # OF	PTS. <u>5</u>
	ANE TO PULL TANK AND BACKHOE	TO SAMPLE.	·	
NO VISU/	AL EVIDENCE OF RELEASE.			·
EXCAVATION DIMENSIONS (if applicable)	NA ft X NA	ft. X NA ft.	cubic yard	Is excavated (if applicable):
SITE SKETCH		OVM CAMB. READ. =ppm	RF = 2.52	PLOT PLAN circle: Attached
		OVAVCALIB. GAS =ppm =		onoic. Attachica
		JME: am/pm JATE:		MISCELL. NOTES
	\oplus		sı	DEWALLS NOT VISIBLE.
	WELL HEAD		$N \frac{3}{2}$	
			' sı	W - SINGLE WALLED.
			DI	B - DOUBLE BOTTOM.
	•		<u> </u>	
	300	300	1_	
,	AST	AST		
	PBGTL x			
	T.B. ~ 5' ────── (x x x)			,
	B.G.			
			l M	AGNETIC DECLINATION @ 10°
		X - S.		OMPARED TO PREVOUSLY
	VATION DEPRESSION; B.G. = BELOW GRADE; B	= BELOW; T.H. = TEST HOLE; ~ = APPROX	<u>ς,</u>] Γυ	SED 13.5°
TRAVEL NOTES: CALLOUT:	BELOW-GRADE TANK LOCATION; SPD = SAMP	LE POINT DESIGNATION; R.W. = RETAININ ONSITE: 07/29/10	IO VVALLI	
revised: 03/23/10		ONOTE. OTTENTO		BEI1005E.SKF





ANALYTICAL RESULTS

Project:

HEATH GC C #1

Pace Project No. 6083255

Sample: 45 BGT 5-PT	Lab ID: 6083	3255001	Collected: 07/29/1	0 12:3	0 Received: 08	3/05/10 08:45 N	latrix, Solid	•
Results reported on a "dry-weight	" basis							
Parameters	'Results	Units	Report Limit	DF"	Prepared	Analyzed	CAS No.	Qúal
8015B Diesel Range Organics	Analytical Meth	- od: EPA 801	5B Preparation Me	thod:-E	ĒPĀ 3546			
TPH-DRO	NDimg	/kg	10.3	Á	08/09/10 00:00	08/12/10 13:04		
n-Tetracosane (S)	91.5%		41-130	1	08/09/10 00:00	08/12/10 13:04	646-31-1	
p-Terphenyl (S)	85 %		39-130	1	08/09/10 00:00	08/12/10 13:04	92-94-4	ű.
Gasoline Range Organics	Ánalytical Meth	od: ÉPA 801	5B Preparation Me	thod: É	EPA 5035A/5030B			
TPH-GRO	25.0 mg	/kg	10.3	1	08/11/10 00:00	08/12/10 17:18		₫ę.
4-Bromofluorobenzene (S)	114, %	•	68-134	Ť	08/11/10,00:00	08/12/10 17:18	460-00-4	
8260 MSV 5035A VOA	Analytical Meth	od: EPA 826	Ď					
Benzene	.ÑD; igg/	kg	-5∖∄	ď		08/09/10 18:32	71-43-2	
Ethylbenzene	'ND' jug/	kg	5!1	1		08/09/10 18:32	100-41-4	
Toluene	ND. ug/		5.1	1		08/09/10 18:32	108-88-3	
Xylene (Total)	ND. ug/	kg	5.1	1		08/09/10 18:32	1330-20-7	
Dibromofluoromethane (S)	98: %	=	68-129	1		08/09/10 18:32	1868-53-7	
Tolueñe-d8 (S)	99 .%		(81-121	1		08/09/10 10:32		
4-Bromofluorobenzene (S)	98 %,		75-131	1		08/09/10 18:32	460-00-4	
1,2-Dichloroethane-d4 (S)	107. %		77-131	প্র		08/09/10 18:32	17060-07-0	
Percent Moisture	Analytical Meth	od: ÁSTM D	2974-87					
Percent Moisture	3.6 %		0.50	á		08/10/10 00:00		
9071 HEM TPH in Soil	Analytical Meth	od: EPA 907	B Preparation Me	thọd: E	PA 9071B			
Total Petroleum Hydrocarbons	:260 mg	/kg	260	1	08/10/10 00:00	08/11/10 00:00		
300.0 IC Anions 28 Days	Analytical Meth	od: EPA 300.	Ò					
Chloride	ND mĝ	/kg	104	10		08/16/10 13:47	16887-00-6	

Date: 08/17/2010 04:57 PM

REPORT OF LABORATORY ANALYSIS.

This report shall not be reproduced, except in full, without the written consent of Pace Analytical Services, Inc.



Page 11 of 19



QUALITY CONTROL DATA

Project:

HEATH GC C #1

Pace Project No.:

6083255

QC Batch:

OEXT/24933

EPA 3546

Analysis Method:

EPA 8015B

QC Batch Method;

Associated Lab Samples:

6083255001

Analysis Description:

EPA 8015B

Qualifiers

METHOD BLANK: 683415

Matrix: Solid

Associated Lab Samples: 6083255001

Paraméter	Units	Blank Result	Reporting Limit	Analyzed
TPH-DRO	mg/kg	ND	9.9	08/12/10 11:35
n-Tetracosane (S)	%	127	41-130	08/12/10 11:35
n-Temberryl (S)	%	.107	39-130	.08/12/10 11:35

LABORATORY CONTROL SAMPLE:

Parameter	Units	Spike Conc.	LCS Result	⊵CS % Rec	% Rec Limits	Qualifiers
TPH-DRO	mg/kg	82.7	68.6	83	57-120	
n-Tetracosane (S)	%			88	41-130	
p-Terphonyl (S)	%			.89	39-130	

MATRIX	SPIKE/&	MATRIX	SPIKE DI	JPLICATE:

683417


683418

Parameter	. 6ļ Ųnits	083111002 Result	MS Spike Conc.	MSD Spike Conc.	MS Result	MSD Result	MS % Rec	MSD % Rec	% Rec Limits	Ņ RPD R	Max RPD	Qual
TPH-DRO n-Tetracosane (S) p-Terphenyl (S)	mg/kg % %-	ДЙ	98.9	99,1	79.4	81;3	77 88 87	79 89 89	-36-125 -41-130 -39-130	•	28	

Date: 08/17/2010 04:57 PM

REPORT OF LABORATORY ANALYSIS

Págo:12 or 19







QUALITY CONTROL DATA

Project: HEATH Pace Project No.: 6083258									
	386 335AV5030B 6083255001	Analysis M Analysis D		PÁ 8015B asoline Ran	ge Organics			, -	
METHOD BLANK: 685240		Mați	ix: Şolid	·			-		
Associated Lab Samples:	6083255001 Units	Blank Result	Reporting Limit	Analyze	ed: 'Qùa	lifièrs			
TPH-GRO 4-Bromofluorobenzene (\$)	mg/kg %	·Ñi 9	D 10,0 9 68-134						
METHOD BLANK: 685901	<u> </u>	Matri	ix: Solid	· · - ·					
	6083255001'	'Blank Result	Reporting Limit	Anályze	id Öuä	ifiers.			
TPH-GRO 4:Bromofluoropenzene (S)	mg/kg %	NI 8	D 10:0	08/15/10 1	3:49	····			
LABORÁTORY CONTROL S		Spike	.LÇ\$	LĈS	% Rec				The state of the s
Parameter	Units	Conc.		% Rec	Limits	Qualifie	<u>.</u>		
TPH-GRO 4-Bromofluorobejízene (S)	mg/kg %	-50	<u>59</u> ,9	120 104	77-122 68-134				
LABORATORY:CONTROL SA	AMPLE: 685902	0.31	100	LCS	% Rec.		 		 -
Parameter	Units	Spike Conc.	LCS Result	⊬Rec	Limits	Quảlifie	ş		
TPH-GRO 4-Bromofluorobenzene (S)	mg/kg %.	50	55.5	711 ⁷ 91	77-122 68-134				
MATRIX SPIKE & MATRIX SI	I PIKE DUPLICATE: 68524	12	685243		<u> </u>	· 			
- Rarameter	6083548001 Units Result	MS M Spike Sp	ŠĎ pike MŠ pnc. Řesult	MSD Result		SD %R		Max RPD	Quai
TPH-GRO	mg/kg, ND %	52.6	52.6 71.7	66.2	136 101	126 51-	130 8 134		MŌ

Date: 08/17/2010 04:57 PM

REPORT OF LABORATORY ANALYSIS

Pàge 13 of 19

This report shall not be reproduced, except in full, without the written consent of Pace Analytical Services, Inc...





QUALITY CONTROL DATA

Project.

HEATH GC C#1

Pace Project No.:

6083255

QC Batch:

MSV/30917

QC Batch Method:

EPA 8260

Associated Lab Samples: 6083255001 Analysis Method:

EPA 8260

Analysis Description:

8260 MSV 5035A Volatile Organics

METHOD BLANK: .683485

Matrix: Solid

Associated Lab Samples:

6083255001

Rarameter	Units	Blank Result	Reporting Limit	Analyzed	Qualifiers
Benzene.	ug/kg	ND.	5.0	08/09/10 12:45	
Ethylbenzene	ug/kg	ND	5.0	08/09/10 12:45	
Toluene	ug/kg	ND	5:0	08/09/10 12:45	
Xylene (Total)	ug/kĝ	ND	5.0	08/09/10 12:45	
1,2-Dichloroethañe-d4 (S)	%	103	77-131	08/09/10 12:45	
4-Bromofluorobenzene (S)	.%	104	75-131	08/09/10 12:45	
Dibromofluoromethane (S)	.%	89	68-129	08/09/10 12:45	
Toluene-d8 (S)	%	95	81-121	08/09/10 12:45	

LABORATORY CONTROL SAMPLE	≘: 683486	v		Ť		2.	
Parameter	.Ur	nils	Spike Conc	LCS Result	LCS % Rec	% Rec Limits	Qualifiers
Benzene	ug/kg	h	100	94.1	194	84-119	
Ethýlbenzeně	ug/kg		100	93.0	.93	80-120	
Toluenç	ug/kg	,	100	92.6	93	83-117	
Xylene (Total)	ug/kg		300	285	95	80-120	
1,2-Dichloroethane-d4 (S)	%	1			101	77-131	
4-Bromofluorobenzene (S)	%				9 7	75-131	
Dibromofluoromethane (S)	%.				101	68-129.	
Toluene-d8 (S)	%				101	<u> 81-121</u>	

MATRIX SPIKE & MATRIX SI	PIKE DUPLICAT	E: '68348		-	683488				-		_	
Parameter		83300001	MS Spike	MSD Spike	MS Result	MSD Result	MS % Rec	MŜD % Rec:	% Rec	RPD	Max RPD	آدنين
	Units	Result	Çonc.	Conc.	resuit		76 Rec			مستنتح	<u> </u>	Qual
Benzene	ug/kg	ŊD	108	93.1	87.2	54.2	:81⁻	58	28-145	47	35	D6
Ethylbenzene	uġ/kg	ND	108	93.1	83 9	50.0	78	54	20-141	51	,39	Ď6
Toluene	ug/kg	ND	108	93.1	84.5	52:5	78	56	19-148		37	D6
Xylene (Total)	ûg/kg	ND	323	279	250	146	77	-52	10-140	•53	39	D6,R1
1,2-Dichloroethane-d4 (S)	%						109	412	77-131			·
4-Bromofluorobenzene (S)	%	j					101	98	75-131			
Dibromofluoromethane (S)	% %	Ĭ					104	106	68-129	,		
Toluene-d8 (S)	%	ļ	t				101	100	81-121			

Date: 08/17/2010 04:57 PM

REPORT OF LABORATORY ANALYSIS

This report shall not be reproduced, except in full, without the written consent of Pace Analytical Services, Inc.



Page 14 of 19



QUALITY CONTROL DATA

Project: Pace Project No.: HEATH GC C #1

6083255

QC Batch:

PMST/5327

QC Batch Method:

ASTM D2974-87

Analysis Method:

ASTM D2974-87

Analysis Description:

Dry Weight/Percent Moisture

Associated Lab Samples:

6083255001

'Matrix: Solid

METHOD BLANK: 684089 Associated Lab Samples:

6083255001

Blank

Reporting

Parameter

Units

Units

Result

Limit

Analyzed

Qualifiers

Percent Moisture

%

IND

08/10/10 00:00

SAMPLE DUPLICATE.

Parameter

6083159008 Result

Dup

Result

RPD

Max RPD

Qualifiers

Percent Moisture

%

16:6

17.0

20

Dale, 08/17/2010 04:57 PM

REPORT OF LABORATORY ANALYSIS

This report shall not be reproduced, except in full, without the written consent of Paco Analytical Sarvicas, Inc..



Page 15:01:10

Page 15 of 21



QUALITY CONTROL DATA

÷.				
Ρi	S	2	~1	•
, .,	~	C	UL:	

HEATH GC C#1

Pace Project No.:

6083255

QC Batch:

WET/24762

QC Batch Method:

EPA 9071B.

Associated Lab Samples: (6083255001 Analysis Method:

EPA 9071B

Analysis Description:

9071B HEM-TPH Gravimetric

METHOD BLANK: 683376

Associated Lab Samples:

Matrix: Solid

6083255001

Blank Result Reporting Limit

Analyzed

Qualifiers

Total Petroleum Hydrocarbons

Parameter

Units mg/kg

mg/kg

ŇD

08/11/10 00:00

LABORATORY CONTROL SAMPLE: 683377

Parameter Total Petroleum Hydrocarbons Units:

Spike Conc. 2010

LCS Result 2620

414

LCS % Rec 131 % Rec Limits 67-135

Qualifiers

MATRIX SPIKE SAMPLE: 683378

Parameter Units Total Petroleum Hydrocarbons mg/kg

6083254001 Result

Spike Conc. 2140

MS Result

MŚ % Rec 149

% Rec Limits

Qualifiers

SAMPLE DUPLICATE: 683379

Total Petroleum I lydrocarbons

Parameter:

Units! mg/kg

6083255001 Résult

:260

Dup Result

154J

RPD

3600

Max RPD

Qualifiers

53-150

42

Date: 08/17/2010 04:57 PM

REPORT OF LABORATORY ANALYSIS

This report shall not be reproduced, except in full, without the written consent of Pace Analytical Services, Inc.



Page 10 of 19



QUALITY CONTROL DATA

Pace Project No.:	
Pace Project No.:	

HEATH GC C #1

6083255

QC Batch:

WETA/13686

QC Batch Method: Associated Lab Samples: 6083255001

EPA 300.0

Analysis Method:

EPA 300.0

Analysis Description:

300.0 IC Anions

METHOD BLANK: 685971 Associated Lab Samples:

6083255001

Blank

Result

Reporting

Matrix: Solid

Limit

Analyzed

Qualifiers

Chloride

mg/kg

ND

10.0 08/16/10 11:08

LABORATORY CONTROL SAMPLE:

Parameter

Parameter

Parameter.

Units :

Spike Conc.

LCS Result

LCS % Rec 102 % Rec Limits

Qualifiers

Chloride

Chloride

mg/kg

Units

mg/kg

50.9

685974

90-110

MATRIX SPIKE & MATRIX SPIKE DUPLICATE:

685973

Result

143

MS Spike 6083294001 Conc.

500

MŞĎ Spike Conc.

500

MS MSD Résult Result 588

MS. % Rec 89 583

MSD % Řec

'% Réc Limits

Max RPD RPD 64-120

15

Qual


Date: 08/17/2010 04:57 PM

REPORT OF LABORATORY ANALYSIS

This report shall not be reproduced, except in full; without the willen consent of Pace Analytical Services, Inc.



Page 17 of 19





QUALITY CONTROL DATA CROSS REFERENCE TABLE

Project:

HEATH GC C #1

Pace Project No.:

6083255

Lab ID 6083255001 6083255001 6083255001	Sample ID	QC Batch Method	QC Batch	Analytical Method	Analytical Batch
6083255001	45 BGT 5-PT	EPA 3546	OEXT/24933	EPA 8015B	GCSV/9166
6083255001	45 BGT 5-PT	EPA 5035A/5030B	GCV/3386	EPA 8015B	GCV/3387
6083255001	45 BGT 5-PT	EPA 8260	MSV/30917		
6083255001	45:BGT 5-PT	ASTM D2974-87	PMST/5327		
6083255001	45 BGT 5-PT	EPA 9071B	WET/24762	EPA 907-1B	WE1/24816
6083255001	45 BGT 5-PT	EPA 300.0	WETA/13686		

Dulo: 08/17/2010 01.57 PM

REPORT OF LABORATORY ANALYSIS

Page 19 of 19

This reprint shall not be reproduced, except in full, without the written consent of Pace Analytical Services, Inc.



	Sample Condition	n Upon Receipt		
Pace Analytical Client Na	ame: BP	Rleas	Project #	5
Olicitie				-
Courier: Fed Ex UPS USPS [Pace Dther	Optional Proj. Due Date:	<u> </u>
Tracking #: <u>264 8408 9977</u>	Pace Shipping Label Use		Proj. Name:	
******		s intact: Yes [No L	
	ubble BagsFoam	None Dther		_
Thermometer Used: T-191 / T-194	Type of Ice: We	Blue None	Samples on ice, cooling process has begur Date and initials of person examining	<u>-</u> -
Cooler Temperature: 47 Temperature should be above freezing to 6°C		Comments:	contents: 8/5/10 15	
Chain of Custody present:	Dives □No □N//	11.		
Chain of Custody filled out:	Yes ONo ON	1		
Chain of Custody relinquished:	Ores One Only	3.		- 1
Sampler name & signature on COC.	Dyes ONo ON/	4		
Samples arrived within holding time:	Yes ONo ON	5.		
Short Hold Time analyses (<72hr):	☐Yes ☐No ☐NI	6.		
Rush Turn Around Time requested:	☐Yes DNo ☐N/	7.		
Sufficient volume:	Dres ONO ONIA	8	· · · · · · · · · · · · · · · · · · ·	
Correct containers used:	ØYes □No □N/A	1		(
-Pace containers used:	Yes No ONIA			
Containers intact:	Yes No DNA	10.		<u>-</u> ;
Unpreserved 5035A soils frozen w/in 48hrs?	Yes No ZNIA	<u> 11. </u>		
Filtered volume received for dissolved tests	☐Yes ☐No ☐N/A	 		
Sample labels match COC:	TYes □No □NA	13.		
-Includes date/time/ID/analyses Matri		<u> </u>	 	
All containers needing preservation have been checke	i maring rande armin	14.		
All containers needing preservation are found to be compliance with EPA recommendation.	in tres the tree			
Exceptions (VOA) ofform, TOC, O&G, WI-DRO (water), Phenolics	Dres □No	Initial when completed	Lot # of added preservative	
Trip Blank present:	TYes No DNA	15.		
Pace Trip Blank lot # (if purchased):				
Headspace in VOA vials (>6mm):	☐Yes ☐No ØNA	16.		
Project sampled in USDA Regulated Area.	OYES ONO ONIA	17. List State: 17. List State:	1	
Client Notification/ Resolution:	Copy,COC to,Client?	Ý / N	Field Data Required? Y / N	
Person Contacted:	Date/	Time:		
Comments/ Resolution:		·.		<u> </u>
•				
· · · · · · · · · · · · · · · · · · ·	<u> </u>		<u> </u>	
			 	
Project Manager Review: NW RE	(G)()	····	Date: 8 A (()	
Tribing ingligible Tealers' 13'000 7'2			Since At 1	
Note: Whenever there is a discrepancy affecting N Certification Office (i.e fout of hold, incorrect prese	orth Carolina compliance san rvative, out of temp, incorrect	nples, a copy of this form v	vill be sent to the North Carolina DEHNR	

F-KS-C-003-Rev.05, 19February2010

Chain of Custody Record

Project Name:
(BP BUAR Region/Enfos Segment:
State or Lend Regulatory Agency:

HEATH GC C #1

BP ROJECT PLENSE BILL BLAGGENGE.

eb Name:	PACE ANALYTICAL					BP/AR Pacility No.:							ota o			onsul	timt/C	ontric	or: B	LAGG EN	R., INC	1	
ddress:	9608 LOIRET BLVD.					BP/AR Facility Add	ress.									ddres	ş:•		11	0 N. 4th ST		· ·	
	LENEXA, KS 66219					Site Let/Long:														.OOMFTEI			
ab PM:	MARY JANE WALLS					California Global II	No:									cosul	tant/C	ontrac	or Pro	ject No.: HE	ATH	fc C #	+1
ole/Fax:	913-563-1401		·—			Enfo: Project No.:														JEFF C.			
P/AR EBI	d:					Provision or OOC (circle	one)			,					elc/Fa	IX:			505-632-1	199		
ddress:			<u> </u>			Phase/WBS:										Cepait	Туро	& QC	Lavel:	STANDA	RD		
						Sub Phase/Task:										-ciail	EDD	To:		jeffeblagg	@noLco	nia .	
ole/Fax:			and the second s		-	Cost Blement:	17-3497									nvolce	tor C	onsul	ant o	BP or Atlantic R	iohfield Co	, (circle one)	
ab Bottle	Order No:			М	etrix				Preser	vativo				Rec	wested								4
Imm Ma	Sámple Déscriptos	Time	Central Portfold - EBM Greg Prisch, Scopes Keith and Christin Kuhlanian Delin UKS PM SIII Chrysin, Stepr I frompitas Beld manager. SAM PLE DATE	Soil/Solid	Air	Laboratory No.	No. of Combiners	Umreserved H ₂ SO ₄	HNO,	HCI .	Methanol	BOIS GRO	8015 DRO	8021 BTEX	CHLORISE BY	Meteral 300	180			D)		335°S Long and Con	-
i	45 BGT 5-P6	1230	7-29-2010	k	TT		П	X	\sqcap			V	X.	×	x	7,	XI	П		146	fu	125	
2	e-5			11	11		Ħ		\Box		1		Ť			+	+	\Box	+	1			
				╁┼	╁	 	Н	÷	╁┤	+	+					+	╁	H	+	 			
-3				╂┼	++		Н	-	+	-	+			-	-	+	+-	\vdash					<u> </u>
4				4	44	<u> </u>	Ц	\perp	Ш	Ш						4	┸	Ц	-1-	<u> </u>			
5	<u> </u>		<u> </u>		Ш										_,			П					
.6											Т					Т.	T	П					
				11	11	1	П	\sqcap	+	T	\top		Ť	-	-	7	+	Н	1	1			
-7		 		╌╂╾╂╴	++		H	\vdash	┿	++	╁			-	-		╁	Н	+				
_8					44	 		\vdash	+-	\vdash	+		_		_	4	4	1	+				
9		ļ		4	-11		L		\perp	Ш	1	L	<u>_</u>				Д.	L		1			
10					$\perp \perp$						1 _			<u> </u>			1						
Sampler	Name: JEFF BLA	GG .				Rolls	-ibb	ni By / A	man n			D	a by	Ť	1000			Ā	cepted 1	By / Afficiation		Deta	7000
Sampler's	Company: BLAGG	NGR, IN	C;			14 B	44	, 1	BE)	Σ.	-	8/1	1/10	15	30		Li	0	1		5	Voto	0849
Shipment	Date: 8/4/2	010	·		<u>. </u>	1	11	·	·				·	_				<u></u>				1	<u></u>
Shipment	Method: FED. EX.	- 									_			<u> </u>	.,	<u> </u>						يـــــــــــــــــــــــــــــــــــــ	ļ
		8408	3977			1						ا		<u>. </u>		۰		~					L
Special In	mtractions:																						
		ustody Scals	In Place: Yes No Temp Blank: A	es this		Cooler Temp on Re			3	-	72.	Blank	V.	(∷)	7 74	00.00	N 6	-1-6	nhonin	ted: Yes No			

