



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

MAR 25 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3-25-15 Operator Burlington API #30-0 39-24518

Property Name SJ 30-6 H. SW Well No. 2 Location: Unit Section 23 Township 30 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 584 Intermediate N/A Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0		0		
10 min	0		.6		
15 min	0		.9		
20 min	0		.9		
25 min	0		1.0		
30 min	0		1.0		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>1</u>	<u>Sus.</u>
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Med light blow when opened - lighter at 3 min
deally light at 7 min - 10 - 15 - 20 - 25 - 30

By David Aguirre
SWD MSD
(Position)

Witness Monica Fuenting
test 4 years

E-mail address