

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

APR 06 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Burlington Resources Oil & Gas Co.	Contact Lindsay Dumas
Address 3401 East 30 th St, Farmington, NM	Telephone No.(505) 599-4089
Facility Name: San Juan 28-6 149N	Facility Type: Gas

Surface Owner: BLM	Mineral Owner: SF-079050-C	API No. 3003929270
--------------------	----------------------------	---------------------------

LOCATION OF RELEASE

Unit Letter G	Section 27	Township 28N	Range 06W	Feet from the 1410'	North/South Line FNL	Feet from the 2570	East/West Line FEL	County Rio Arriba
-------------------------	----------------------	------------------------	---------------------	-------------------------------	--------------------------------	------------------------------	------------------------------	-----------------------------

Latitude **36.635619** Longitude **-107.454675**

NATURE OF RELEASE

Type of Release Hydrocarbon	Volume of Release 14.85 bbl	Volume Recovered 0 bbl
Source of Release Oil/Production Tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 3/24/2015 at 1:30 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Production tank release due to corrosion. COP will delineate to determine a path forward.

Describe Area Affected and Cleanup Action Taken.*

ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Lindsay Dumas</i>	OIL CONSERVATION DIVISION	
Printed Name: Lindsay Dumas	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Environmental Specialist	Approval Date: 4/7/15	Expiration Date:
E-mail Address: Lindsay.Dumas@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/24/2015 Phone: (505) 599-4089		

* Attach Additional Sheets If Necessary

#NCS 1509731577

①