	DEPARTMENT O		EEC 29 201	4	FORM APPROVED OMB No. 1004-0137 Expires: March 31, 2007	
E	SUREAU OF LANI	D MANAGEMENT		5 Looce Sori	•	
SUNDRY	Y NOTICES AND	REPORTS ON W	ELLS,	** NMSF-0783		
		sals to drill <sup>i</sup> or to . 0-3 (APD) for such			Allottee or Tribe Name	
		E – Other instructions or			CA/Agreement, Name and/or No.	
1. Type of Well	•		· · · · · · · · · · · · · · · · · · ·	132829		
Oil Well Gas Well Other				8. Well Name and No. NE CHACO COM #176H		
2. Name of Operator WPX Energy Production, LLC			9. API Well No. 30-039-31251			
3a. Address   3b. Phone No. (iii)		3b. Phone No. (include	de area code) 10. Field and Pool or Exploratory Area		Pool or Exploratory Area	
PO Box 640         Aztec, NM 87410           4. Location of Well (Footage, Sec., T.,R.,M., or Survey D			505-333-1816		CHACO UNIT NE HZ OIL 11. Country or Parish, State	
4. Location of Wen ( <i>Poolage</i> , <i>sec.</i> , <i>1.</i> , <i>R.</i> , <i>M.</i> , <i>or survey Description</i> ) SHL: 1120' FNL & 736' FWL, SEC 6, T23N, R6W BHL: 386' FNL & 229' FWL SEC 1 T23N R7W			Rio Arriba, NM			
12. CHE	CK THE APPROPRIAT	E BOX(ES) TO INDICA	TE NATURE OF NOT	TCE, REPORT O	R OTHER DATA	
TYPE OF SUBMISSION			TYPE OF ACTI	ON		
Notice of Intent	Acidize	Deepen	Production (	(Start/Resume)	Water Shut-Off	
	Alter Casing	Fracture Treat	Reclamation		Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete		Other <u>COMPLETION</u>	
_ y	Change Plans	Plug and Abandon	Temporarily	Abandon	<u></u>	
Notice	Final Abandonment Convert to Plug Back POOL NAME CHANGE					
requirements, including re			is been completed. Fina	l Abandonment N	ults in a multiple completion or otices must be filed only after all inal inspection.)	
requirements, including re <u>11/25/14-</u> MIRU HWS #10 <u>11/26/14-</u> Run Tie Back String- casing, 19.69' X 4 1/2" 11.6# F 3.06 & 1-2.75 & 1- 2.22 P110 1	No-Go, and 4 1/2" 11.6 P110 casing sub/ Marker I jnt sups Total length of	ompleted and the operator # P110 casing as follows; Jt set @ 4489' - 4509', 1: f all Tubulars ran in well =	as been completed. Fina has determined that the Seal Assembly with No 17 Jts 4 1/2" 11.6# P11 5783.66' . Had an up v	I Abandonment N e site is ready for f p-Go 5.85" OD 4.0 0 casing, 1 X 2.50' vt of 59K and dow	otices must be filed only after all inal inspection.) 00" ID, 40 Jts 4 1/2" 11.6# P110 casing sub, and casing hanger, 1- n wt of 50K. Landed with 40K on	
requirements, including re <u>11/25/14-</u> MIRU HWS #10 <u>11/26/14-</u> Run Tie Back String- casing, 19.69' X 4 1/2" 11.6# F 3.06 & 1-2.75 & 1- 2.22 P110 1 liner top and leaving 14K on ha CO to 10764'	No-Go, and 4 1/2" 11.6 P110 casing sub/ Marker I jnt sups Total length of	ompleted and the operator # P110 casing as follows; Jt set @ 4489' - 4509', 1: f all Tubulars ran in well =	as been completed. Fina has determined that the Seal Assembly with No 17 Jts 4 1/2" 11.6# P11 5783.66' . Had an up v	I Abandonment N e site is ready for f p-Go 5.85" OD 4.0 0 casing, 1 X 2.50' vt of 59K and dow	otices must be filed only after all inal inspection.) 00" ID, 40 Jts 4 1/2" 11.6# P110 casing sub, and casing hanger, 1- n wt of 50K. Landed with 40K on or 30 min each,	
requirements, including re <u>11/25/14-</u> MIRU HWS #10 <u>11/26/14-</u> Run Tie Back String- casing, 19.69' X 4 1/2" 11.6# F 3.06 & 1-2.75 & 1- 2.22 P110 1 liner top and leaving 14K on ha CO to 10764'	No-Go, and 4 1/2" 11.6 P110 casing sub/ Marker I jnt sups Total length of	ompleted and the operator # P110 casing as follows; Jt set @ 4489' - 4509', 1: f all Tubulars ran in well =	as been completed. Fina has determined that the Seal Assembly with No 17 Jts 4 1/2" 11.6# P11 5783.66' . Had an up v	I Abandonment N e site is ready for f o-Go 5.85" OD 4.0 0 casing, 1 X 2.50' vt of 59K and dow t good. Charted fo	otices must be filed only after all inal inspection.) 00" ID, 40 Jts 4 1/2" 11.6# P110 casing sub, and casing hanger, 1- n wt of 50K. Landed with 40K on or 30 min each, <b>OIL CONS.</b> DIV DIST	
requirements, including re <b>11/25/14-</b> MIRU HWS #10 <b>11/26/14-</b> Run Tie Back String- casing, 19.69' X 4 1/2" 11.6# F 3.06 & 1-2.75 & 1- 2.22 P110 1 liner top and leaving 14K on ha CO to 10764' <b>11/27/14</b> -RD HWS #10 <b>11/28/14</b> -Perf Gallup 1 <sup>st</sup> stage	eclamation, have been co No-Go, and 4 1/2" 11.6 P110 casing sub/ Marker I jnt sups Total length of anger. Pressure test 4.5'	mpleted and the operator # P110 casing as follows; Jt set @ 4489' - 4509', 1: fall Tubulars ran in well = ' casing to 1600 psi and 4	as been completed. Fina has determined that the Seal Assembly with No 17 Jts 4 1/2" 11.6# P11 5783.66' . Had an up v .5" x 7" to 1500 psi, tes	I Abandonment N e site is ready for f o-Go 5.85" OD 4.0 0 casing, 1 X 2.50' vt of 59K and dow t good. Charted fo	otices must be filed only after all inal inspection.) 00" ID, 40 Jts 4 1/2" 11.6# P110 casing sub, and casing hanger, 1- n wt of 50K. Landed with 40K on or 30 min each, <b>OIL CONS.</b> DIV DIST	
requirements, including re <u>11/25/14-</u> MIRU HWS #10 <u>11/26/14-</u> Run Tie Back String- casing, 19.69' X 4 1/2" 11.6# F 3.06 & 1-2.75 & 1- 2.22 P110 1 liner top and leaving 14K on ha CO to 10764' <u>11/27/14</u> -RD HWS #10 <u>11/28/14</u> -Perf Gallup 1 <sup>st</sup> stage	eclamation, have been co No-Go, and 4 1/2" 11.6 P110 casing sub/ Marker I jnt sups Total length of anger. Pressure test 4.5' 9, 10579'-10704' + RSI TC	mpleted and the operator # P110 casing as follows; Jt set @ 4489' - 4509', 1: fall Tubulars ran in well = ' casing to 1600 psi and 4	as been completed. Fina has determined that the Seal Assembly with No 17 Jts 4 1/2" 11.6# P11 5783.66' . Had an up v .5" x 7" to 1500 psi, tes	I Abandonment N e site is ready for f o-Go 5.85" OD 4.0 0 casing, 1 X 2.50' vt of 59K and dow t good. Charted fo	otices must be filed only after all inal inspection.) 00" ID, 40 Jts 4 1/2" 11.6# P110 casing sub, and casing hanger, 1- n wt of 50K. Landed with 40K on or 30 min each,	
requirements, including re <u>11/25/14-</u> MIRU HWS #10 <u>11/26/14-</u> Run Tie Back String- casing, 19.69' X 4 1/2" 11.6# F 3.06 & 1-2.75 & 1- 2.22 P110 1 liner top and leaving 14K on ha CO to 10764' <u>11/27/14</u> -RD HWS #10 <u>11/28/14</u> -Perf Gallup 1 <sup>st</sup> stage <u>11/29/14-12/1/14</u> - prepare fo	eclamation, have been co No-Go, and 4 1/2" 11.6 P110 casing sub/ Marker I jnt sups Total length of anger. Pressure test 4.5' 9, 10579'-10704' + RSI TC	mpleted and the operator # P110 casing as follows; Jt set @ 4489' - 4509', 1: fall Tubulars ran in well = ' casing to 1600 psi and 4	as been completed. Fina has determined that the Seal Assembly with No 17 Jts 4 1/2" 11.6# P11 5783.66' . Had an up v .5" x 7" to 1500 psi, tes	I Abandonment N e site is ready for f o-Go 5.85" OD 4.0 0 casing, 1 X 2.50' vt of 59K and dow t good. Charted fo	otices must be filed only after all inal inspection.) 00" ID, 40 Jts 4 1/2" 11.6# P110 casing sub, and casing hanger, 1- n wt of 50K. Landed with 40K on or 30 min each, <b>OIL CONS.</b> DIV DIST	
requirements, including re <u>11/25/14-</u> MIRU HWS #10 <u>11/26/14-</u> Run Tie Back String- casing, 19.69' X 4 1/2" 11.6# F 3.06 & 1-2.75 & 1- 2.22 P110 1 liner top and leaving 14K on ha CO to 10764' <u>11/27/14</u> -RD HWS #10 <u>11/28/14</u> -Perf Gallup 1 <sup>st</sup> stage <u>11/29/14-12/1/14</u> - prepare fo <u>14. I hereby certify that the foreg</u> Name ( <i>Printed/Typed</i> )	eclamation, have been co No-Go, and 4 1/2" 11.6 P110 casing sub/ Marker I jnt sups Total length of anger. Pressure test 4.5' 9, 10579'-10704' + RSI TC	mpleted and the operator # P110 casing as follows; Jt set @ 4489' - 4509', 1: fall Tubulars ran in well = ' casing to 1600 psi and 4. DOL @10764'- 10767' with	as been completed. Fina has determined that the Seal Assembly with No 17 Jts 4 1/2" 11.6# P11 5783.66' . Had an up v .5" x 7" to 1500 psi, tes	I Abandonment N e site is ready for f o-Go 5.85" OD 4.0 0 casing, 1 X 2.50' vt of 59K and dow t good. Charted fo	otices must be filed only after all inal inspection.) 00" ID, 40 Jts 4 1/2" 11.6# P110 casing sub, and casing hanger, 1- n wt of 50K. Landed with 40K on or 30 min each, <b>OIL CONS.</b> DIV DIST	
requirements, including re <u>11/25/14-</u> MIRU HWS #10 <u>11/26/14-</u> Run Tie Back String- casing, 19.69' X 4 1/2" 11.6# F 3.06 & 1-2.75 & 1- 2.22 P110 1 liner top and leaving 14K on ha CO to 10764' <u>11/27/14</u> -RD HWS #10 <u>11/28/14</u> -Perf Gallup 1 <sup>st</sup> stage <u>11/29/14-12/1/14</u> - prepare fo <u>14. I hereby certify that the foregore</u> Name ( <i>Printed/Typed</i> ) Lacey Granillo	eclamation, have been co No-Go, and 4 1/2" 11.6 P110 casing sub/ Marker I jnt sups Total length of anger. Pressure test 4.5' 9, 10579'-10704' + RSI TC	mpleted and the operator # P110 casing as follows; Jt set @ 4489' - 4509', 1: f all Tubulars ran in well = ' casing to 1600 psi and 4 DOL @10764'- 10767' with	as been completed. Fina has determined that the Seal Assembly with No 17 Jts 4 1/2" 11.6# P11 5783.66'. Had an up v .5" x 7" to 1500 psi, tes h 18, 0.40" holes	I Abandonment N e site is ready for f o-Go 5.85" OD 4.0 0 casing, 1 X 2.50' vt of 59K and dow t good. Charted fo	otices must be filed only after all inal inspection.) 00" ID, 40 Jts 4 1/2" 11.6# P110 casing sub, and casing hanger, 1- n wt of 50K. Landed with 40K on or 30 min each, <b>OIL CONS.</b> DIV DIST	
requirements, including re <u>11/25/14-</u> MIRU HWS #10 <u>11/26/14-</u> Run Tie Back String- casing, 19.69' X 4 1/2" 11.6# F 3.06 & 1-2.75 & 1- 2.22 P110 1 liner top and leaving 14K on ha CO to 10764' <u>11/27/14</u> -RD HWS #10 <u>11/28/14</u> -Perf Gallup 1 <sup>st</sup> stage <u>11/29/14-12/1/14</u> - prepare fo <u>14. I hereby certify that the foreg</u> Name ( <i>Printed/Typed</i> )	eclamation, have been co No-Go, and 4 1/2" 11.6 P110 casing sub/ Marker 1 jnt sups Total length of anger. Pressure test 4.5' 2, 10579'-10704' + RSI TC or frac	mpleted and the operator # P110 casing as follows; Jt set @ 4489' - 4509', 1: fall Tubulars ran in well = casing to 1600 psi and 4 DOL @10764'- 10767' with Tit	as been completed. Fina has determined that the Seal Assembly with No 17 Jts 4 1/2" 11.6# P11 5783.66'. Had an up v .5" x 7" to 1500 psi, tes h 18, 0.40" holes le Permit Tech III te 12/29/14	Abandonment N e site is ready for f o-Go 5.85" OD 4.0 0 casing, 1 X 2.50' vt of 59K and dow t good. Charted for	otices must be filed only after all inal inspection.) 00" ID, 40 Jts 4 1/2" 11.6# P110 casing sub, and casing hanger, 1- n wt of 50K. Landed with 40K on or 30 min each, <b>OIL CONS.</b> DIV DIST	
requirements, including re 11/25/14- MIRU HWS #10 11/26/14-Run Tie Back String- casing, 19.69' X 4 1/2" 11.6# F 3.06 & 1-2.75 & 1- 2.22 P110 1 liner top and leaving 14K on ha CO to 10764' 11/27/14-RD HWS #10 11/28/14-Perf Gallup 1 <sup>st</sup> stage 11/29/14-12/1/14- prepare fo Name ( <i>Printed/Typed</i> ) Lacey Granillo Signature	eclamation, have been co No-Go, and 4 1/2" 11.6 P110 casing sub/ Marker 1 jnt sups Total length of anger. Pressure test 4.5' 2, 10579'-10704' + RSI TC or frac	mpleted and the operator # P110 casing as follows; Jt set @ 4489' - 4509', 1: f all Tubulars ran in well = ' casing to 1600 psi and 4 DOL @10764'- 10767' with	as been completed. Fina has determined that the Seal Assembly with No 17 Jts 4 1/2" 11.6# P11 5783.66'. Had an up v .5" x 7" to 1500 psi, tes h 18, 0.40" holes le Permit Tech III te 12/29/14	Abandonment N e site is ready for f o-Go 5.85" OD 4.0 0 casing, 1 X 2.50' vt of 59K and dow t good. Charted for	otices must be filed only after all inal inspection.) 00" ID, 40 Jts 4 1/2" 11.6# P110 casing sub, and casing hanger, 1- n wt of 50K. Landed with 40K on or 30 min each, <b>OIL CONS.</b> DIV DIST	
requirements, including re 11/25/14- MIRU HWS #10 11/26/14-Run Tie Back String- casing, 19.69' X 4 1/2" 11.6# F 3.06 & 1-2.75 & 1- 2.22 P110 1 liner top and leaving 14K on ha CO to 10764' 11/27/14-RD HWS #10 11/28/14-Perf Gallup 1 <sup>st</sup> stage 11/29/14-12/1/14- prepare fo Name ( <i>Printed/Typed</i> ) Lacey Granillo Signature	eclamation, have been co No-Go, and 4 1/2" 11.6 P110 casing sub/ Marker 1 jnt sups Total length of anger. Pressure test 4.5' 2, 10579'-10704' + RSI TC or frac	mpleted and the operator # P110 casing as follows; Jt set @ 4489' - 4509', 1: fall Tubulars ran in well = casing to 1600 psi and 4 DOL @10764'- 10767' with Tit	as been completed. Fina has determined that the Seal Assembly with No 17 Jts 4 1/2" 11.6# P11 5783.66'. Had an up v .5" x 7" to 1500 psi, tes h 18, 0.40" holes le Permit Tech III te 12/29/14	Abandonment N e site is ready for f o-Go 5.85" OD 4.0 0 casing, 1 X 2.50' vt of 59K and dow t good. Charted for	otices must be filed only after all inal inspection.) 00" ID, 40 Jts 4 1/2" 11.6# P110 casing sub, and casing hanger, 1- n wt of 50K. Landed with 40K on or 30 min each, <b>OIL CONS.</b> DIV DIST	
requirements, including re 11/25/14- MIRU HWS #10 11/26/14-Run Tie Back String- casing, 19.69' X 4 1/2" 11.6# F 3.06 & 1-2.75 & 1-2.22 P110 1 liner top and leaving 14K on ha CO to 10764' 11/27/14-RD HWS #10 11/28/14-Perf Gallup 1 <sup>st</sup> stage 11/29/14-12/1/14- prepare for I4. I hereby certify that the foreg Name ( <i>Printed/Typed</i> ) Lacey Granillo Signature Approved by Conditions of approval, if any, ar or certify that the applicant holds	eclamation, have been co No-Go, and 4 1/2" 11.6 P110 casing sub/ Marker 1 jnt sups Total length of anger. Pressure test 4.5' 2, 10579'-10704' + RSI TC or frac coing is true and correct.	mpleted and the operator # P110 casing as follows; Jt set @ 4489' - 4509', 1: f all Tubulars ran in well = ' casing to 1600 psi and 4 DOL @10764'- 10767' with DOL @10764'- 10767' with Tit Da CE FOR FEDERA	as been completed. Fina has determined that the Seal Assembly with No 17 Jts 4 1/2" 11.6# P11 5783.66'. Had an up v .5" x 7" to 1500 psi, tes h 18, 0.40" holes le Permit Tech III te 12/29/14 L OR STATE OF	Abandonment N e site is ready for f o-Go 5.85" OD 4.0 0 casing, 1 X 2.50' vt of 59K and dow t good. Charted for CONFIC	otices must be filed only after all inal inspection.) 00" ID, 40 Jts 4 1/2" 11.6# P110 casing sub, and casing hanger, 1- n wt of 50K. Landed with 40K on or 30 min each, <b>OIL CONS.</b> DIV DIST DENTIAL	
requirements, including re 11/25/14- MIRU HWS #10 11/26/14-Run Tie Back String- casing, 19.69' X 4 1/2" 11.6# F 3.06 & 1-2.75 & 1- 2.22 P110 1 liner top and leaving 14K on ha CO to 10764' 11/27/14-RD HWS #10 11/28/14-Perf Gallup 1 <sup>st</sup> stage 11/29/14-12/1/14- prepare fo Name ( <i>Printed/Typed</i> ) Lacey Granillo Signature Approved by Conditions of approval, if any, ar or certify that the applicant holds ease which would entitle the app Fitle 18 U.S.C. Section 1001 and	eclamation, have been co No-Go, and 4 1/2" 11.6 P110 casing sub/ Marker 1 jnt sups Total length of anger. Pressure test 4.5" c, 10579'-10704' + RSI TC or frac going is true and correct.	mpleted and the operator # P110 casing as follows; Jt set @ 4489' - 4509', 1: Fall Tubulars ran in well = ' casing to 1600 psi and 4 DOL @10764'- 10767' with DOL @10764'- 10767' with CE FOR FEDERA Lis notice does not warrant those rights in the subject ns thereon. 212, make it a crime for any	as been completed. Fina has determined that the Seal Assembly with No 17 Jts 4 1/2" 11.6# P11 5783.66'. Had an up v .5" x 7" to 1500 psi, tes h 18, 0.40" holes le Permit Tech III te 12/29/14 L OR STATE OF Title Office	ACCEPTED	otices must be filed only after all inal inspection.) 00" ID, 40 Jts 4 1/2" 11.6# P110 casing sub, and casing hanger, 1- n wt of 50K. Landed with 40K on r 30 min each, <b>OIL CONS.</b> DIV DIST DENTIALAN 6 9 2015 DENTIAL	
requirements, including re 11/25/14- MIRU HWS #10 11/26/14-Run Tie Back String- casing, 19.69' X 4 1/2" 11.6# F 3.06 & 1-2.75 & 1-2.22 P110 1 liner top and leaving 14K on ha CO to 10764' 11/27/14-RD HWS #10 11/28/14-Perf Gallup 1 <sup>st</sup> stage 11/29/14-12/1/14- prepare fo I4. I hereby certify that the foreg Name ( <i>Printed/Typed</i> ) Lacey Granillo Signature Approved by Conditions of approval, if any, ar or certify that the applicant holds ease which would entitle the app	eclamation, have been co No-Go, and 4 1/2" 11.6 P110 casing sub/ Marker 1 jnt sups Total length of anger. Pressure test 4.5' b, 10579'-10704' + RSI TO or frac going is true and correct. HIS SPA e attached. Approval of the legal or equitable title to plicant to conduct operatio I Title 43 U.S.C. Section 1 s or fraudulent statements of	mpleted and the operator # P110 casing as follows; It set @ 4489' - 4509', 1: fall Tubulars ran in well = ' casing to 1600 psi and 4 DOL @10764'- 10767' with DOL @10764'- 10767'	as been completed. Fina has determined that the Seal Assembly with No 17 Jts 4 1/2" 11.6# P11 5783.66'. Had an up v .5" x 7" to 1500 psi, tes h 18, 0.40" holes h 18, 0.40" holes	ACCEPTED	otices must be filed only after all inal inspection.) 00" ID, 40 Jts 4 1/2" 11.6# P110 casing sub, and casing hanger, 1- n wt of 50K. Landed with 40K on or 30 min each, <b>OBL CONS</b> . DIV DIST DENTIAL AN 6 9 2015 DENTIAL	

.

•

л Т

## NE CHACO COM #176H – page 2

## **<u>12/2/14-</u>**Frac Gallup 1<sup>st</sup> stage 10579'-10767'- with 215,345 # 20/40 PSA Sand

Set flo-thru frac plug @ 10545' MD. Perf 2<sup>nd</sup> 10293'-10479'- with 24 total, 0.40" holes. Frac Gallup 2<sup>nd</sup> stage with 215,809#, 20/40 PSA Sand Set flo-thru frac plug @ 10250' MD. Perf 3<sup>rd</sup> stage 10007'-10193'- with 24, 0.40" holes. Frac Gallup 3<sup>rd</sup> stage with 203,860#, 20/40 PSA Sand Set flo-thru frac plug @ 9980' MD. Perf 4<sup>th</sup> stage 9691'-9907'- with 24, 0.40" holes.

### 12/3/14-12/6/14- wait on equipment

# 12/7/14-Frac Gallup 4<sup>th</sup> stage with 214,356#, 20/40 PSA Sand

Set flo-thru frac plug @ 9640' MD. Perf 5<sup>th</sup> stage 9375'-9601'-with 24, 0.40" holes. Frac Gallup 5<sup>th</sup> stage with 215,978#, 20/40 PSA Sand

12/8/14-Set flo-thru frac plug @ 9340' MD. Perf 6<sup>th</sup> stage 9089'-9275'- with 24, 0.40" holes. Frac Gallup 6<sup>th</sup> stage with 214,937#, 20/40 PSA Sand

Set flo-thru frac plug @ 9060' MD. Perf 7<sup>th</sup> stage 8803'-8989'- with 24, 0.40" holes. Frac Gallup 7<sup>th</sup> stage with 215,408#, 20/40 PSA Sand Set flo-thru frac plug @ 8760' MD. Perf 8<sup>th</sup> stage 8522'-8711'- with 24, 0.40" holes. Frac Gallup 8<sup>th</sup> stage with 215,399#, 20/40 PSA Sand Set flo-thru frac plug @ 8460' MD. Perf 9<sup>th</sup> stage 8231'-8417'- with 24, 0.40" holes.

### 12/9/14-Frac Gallup 9<sup>th</sup> stage with 215,621#, 20/40 PSA Sand

Set flo-thru frac plug @ 8190' MD. Perf 10<sup>th</sup> stage 7950'-8125'- with 24, 0.40" holes. Frac Gallup 10<sup>th</sup> stage with 216,143#, 20/40 PSA Sand Set flo-thru frac plug @ 7890' MD. Perf 11<sup>th</sup> stage 7659'-7845'- with 24, 0.40" holes. Frac Gallup 11<sup>th</sup> stage with 212,000#, 20/40 PSA Sand Set flo-thru frac plug @ 7610' MD. Perf 12<sup>th</sup> stage 7373'-7556'- with 24, 0.40" holes. Frac Gallup 12<sup>th</sup> stage with 265,710# 20/40 PSA Sand Set flo-thru frac plug @ 7320' MD. Perf 13<sup>th</sup> stage 7087'-7279'- with 24, 0.40" holes.

### 12/10/14-Frac Gallup 13<sup>th</sup> stage with 267,871#, 20/40 PSA Sand

Set flo-thru frac plug @ 7055' MD. Perf 14<sup>th</sup> stage 6816'-6987'- with 24, 0.40" holes. Frac Gallup 14<sup>th</sup> stage with 262,200#, 20/40 PSA Sand Set flo-thru frac plug @ 6780' MD. Perf 15<sup>th</sup> stage 6550'-6716'- with 24, 0.40" holes. Frac Gallup 15<sup>th</sup> stage with 273,000#, 20/40 PSA Sand Set flo-thru frac plug @ 6490' MD. Perf 16<sup>th</sup> stage 6259'-6445'- with 24, 0.40" holes. Frac Gallup 16<sup>th</sup> stage with 227,164#, 20/40 PSA Sand Set 4-1/2" CIPB @ 4965'

12/11/14- RDMO Frac & WL.

12/15/14- MIRU HWS #10

12/16/14-TEST BOP, DO CIBP @ 4965', 6490', 6780', 7055' and 7320'

12/17/14-CO to Plug @ 7610'.

12/18/14-DO flo- thru Frac plug @ 7610', 7890', 8190', 8460', 8760', 9060', 9340', 9640', 9980', and 10250'.

**12/19/14-** DO flo thru Frac plug @ 10545'. C/O well to RSI tool @ 10767'. Land well @ 5929' w/ 14.5' KB as follows 1/2 MS, 1 Jt of 2.375" 4.7lbs J55. 8rnd EUE tbg, 1.50" FN @ 5897', 188 Jts of 2.375" 4.7lbs. J55 8rnd EUE tbg, set and LD tbg hanger, BO landing sub. 189 jts 2.375 total.

#### 12-22-14-First delivered Oil to sales.

Choke Size= 1", Tbg Prsr= 300psi, Csg Prsr= 1000 psi, Sep Prsr= 130 psi, Sep Temp= 130 degrees F, Flow Line Temp= 78 degrees F, Flow Rate= 869 mcf/d, 24hr Fluid Avg= 29 bph, 24hr Wtr= 134 bbls, 24hr Wtr Avg= 11 bph, Total Wtr Accum= 744 bbls, 24hr Oil= 218 bbls, 24hr Oil Avg= 18bph, Total Oil Accum= 870 bbls

NOTE: 4-1/2" tie back string from surface to TOL @ 6056' will be removed at a later date when artificial lift is installed in this well.