



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

APR 14 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4/14/2015 Operator XTO API #30-0 45-23784

Property Name EH Pipkin Well No. 9E Location: Unit D Section 35 Township 28 Range 11

Well Status(Shut-In or Producing) Initial PSI: Tubing 51 Intermediate — Casing 53 Bradenhead 44

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	—	54		
10 min	0	—	55		
15 min	0	—	56		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing		
Gas	✓	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR — FRESH — SALTY — SULFUR — BLACK —

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 29 INTERMEDIATE —

REMARKS:

Bradenhead blew down in 6 seconds to a very slight blow.
Gas anal. and well bore schematic requested.

By Robert Mark
Robert Mark
(Position)

Witness Paul Wiebe

E-mail address —