

NEW MEXICO ENERGY, MUNERAILS & NATURAL RESOURCES IDEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

	API#30-0.39-26646
Property Name CANDON LAGO Well No. 451 Location: Unit Section 8 Township Range 4	
Well Status(Shut-In or Producing) Initial PSI: Tubing <u>97</u> Intermediate <u>M</u> Casing <u>30</u> Bradenhead <u>5, 7</u>	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME / 12/	Steady Flow
	Surges
	Nothing (
	Gas Gas & Water
	Water
If bradenhead flowed water, check all of the descriptions that apply below: CLEAR	
5 MINUTE SHUT-IN PRESSURE BRADENHEAD 4 INTERMEDIATE MA	
REMARKS: OPENED THE BAC	DENHEAD AND IT PRODUCED
DOWN TO ZERO IN 55 SE	conos,
By With	ess Stm Dueley
(Position)	OIL CONS. DIV DIST. 3
E-mail address	APR 2 9 2015