



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

BHT #3 2014

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.d.state.nm.us/ocd/Oistrict1W3dIstric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-17-14 Operator Chelon mid cut API #30-0 45-24392

Property Name Cardon.com ^{swd} Well No. 1 Location: Unit 1425 Section 27 Township 32 Range 13

Well Status (Shut-In or Producing) Initial PSI: Tubing 1425 Intermediate 45 Casing -1 Bradenhead 9

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	29	-3	0	-3
10 min	0	28	-3	0	-3
15 min	0	27	-3	0	-3
20 min				0	-3
25 min				0	-3
30 min				0	-3

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	Puff Puff
Nothing	
Gas	
Gas & Water	
Water	

RCVD SEP 19 '14

OIL CONS. DIV.

DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

Braden Head Puff To zero, Daul for Test
Intermediate puff To zero

By Randy Calder
calder service
(Position)

Witness

Monica Cuchlan

E-mail address Randy.C@calderservice.com