

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)				
Date of Test	5-8-1	Operato	· Cherusso. Toll	KAPI #30-0 45-3428Z
Property Name 154 Tah 5 Well No.   Location: Unit Section / Township Z4Range 10				
Well Status(Shut-In or Producing) Initial PSI: Tubing 590 Intermediate ACasing 26 Bradenhead O				
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH				
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg		FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE		
TIME 5 min	22		Steady Flow	
10 min 0	18		Surges	
15 min ( )	15		Down to Nothing	
20 min 0			Nothing	
25 min 0	8		Gas	
30 min /	6		Gas & Water	
		•	Water	
If bradenhead flowed water, check all of the descriptions that apply below:				
CLEAR FRESH SALTY SULFUR BLACK				
5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE				
REMARKS: Well's cusecting-Casing Dusserse (17) Pure				
Wholetest - c (For 24d) for 2 lbs cluring 5, new Thating				
DBH.				
By Juson E Chat Witness / Owla Lulling				
Position) Letest in 30 clays.				
E-mail address				