

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.mn.us/ocd/District III/3distric.htm Ū

OIL CONS. DIV DIST. 3

MAY 1 3 2015

BRADENHEAD TEST REPORT (submit 1 copy to above address)	
•	Nozluain Energis API#30-0 45-34986
Property Name Luby Well No. 2 Location: Unit Section 3 Township 29Range /3	
Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate Casing 2 Bradenhead 25	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
$\begin{array}{c c} \text{TIME} \\ \text{5 min} \\ \hline \hline \hline \\ $	Steady Flow
10 min 0 13	Surges
15 min	Down to Nothing
20 min	Nothing
25 min	Gas
30 min	Gas & Water
· · · · · · · · · · · · · · · · · · ·	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY SULFUR BLACK	
5 MINUTE SHUT-IN PRESSURE BRADENHEAD 22 INTERMEDIATE	
REMARKS: Puff-10 furnes in 2 seconds 60 chead in 5	
pic.	
By Clem R Los Witness // OMCa Cuell end	
(Position)	
E-mail address	