Form 3160-5 (August 2007)

' UNITED STATES DEPARTMENT OF THE INTERIOR PLIPE ALL OF LAND MANAGEMENT

Marie Sand Land of Sand

Copy for commuter fits

FORM APPROVED
OMB No. 1004-0137

DEP	ARTMENT OF THE	THE INTERIOR				pires: July 31.	, 2010	
BUR	AGEMENT	MAY 2		Lease Serial No.				
SUNDRY N	[6	6, If Indian, Allottee or Tribe Name						
	orm for proposals t Use Form 3160-3 (A				- المعارة المالية في المن المن المن المن المن المن المن المن			
SUBMIT	7. If Unit of CA/Agreement, Name and/or No. NMNM-78403A							
l. Type of Well ☑ Oil Well ☐ Gas W	ell Other	OIL CONS. DIV DIST. 3			8. Well Name and No. Northeast Hogback Unit #36			
2. Name of Operator Chuza Oil Company	JUN 4 2014			9. API Well No. 30-045-09622				
3a. Address	3b. Phone No. (include area code)			10. Field and Pool or Exploratory Area			_	
1000 Cordova Place #376, Santa Fe, NM 87505	505-690-7803			Horseshoe Gallup				
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)					11. Country or Parish, State			
160' FSL 1730' FEL Sec. 10 T30N R16W					San Juan County, N	ew Mexico		
12. CHEC	K THE APPROPRIATE BO	X(ES) TO INDICATE	E NATURE OF	NOTICE	E, REPORT OR OTHE	ER DATA		_
TYPE OF SUBMISSION	TYPE OF ACT				NC			
Notice of Intent	Acidize	Deepen		Produc	ction (Start/Resume)	Water	r Shut-Off	_
Notice of finem	Alter Casing	Fracture Trea	at	Reclan	nation	Well I	Integrity	
Subsequent Report	Casing Repair	New Constru	iction	Recom	plete	✓ Other	well communication	1
	Change Plans	Plug and Aba	andon	Tempo	rarily Abandon	****		_
Final Abandonment Notice	Convert to Injection	tion Plug Back		Water	Disposal			
Describe Proposed or Completed Op the proposal is to deepen directiona Attach the Bond under which the w	illy or recomplete horizontal	ly, give subsurface loca	ations and meas	ured and	true vertical depths of	f all pertinent	markers and zones.	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. It the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

On April 10th, 2014, Chuza Oil Company began stimulation and completion operations on the Northeast Hogback Unit #74H (API 30-045-34755). Baker Hughes was contracted to provide hydraulic fracturing services based on Chuza Oil Company's 15-stage treatment design. The last stage of hydraulic fracturing operation was completed at approximately 9pm on April 12th, and all frac equipment was moved off location on April 13th.

Prior to the commencement of the hydraulic fracturing operations, all production equipment was removed from the Northeast Hogback Unit #36. Additionally, a retrievable bridge plug was set above the perforations and the casing was loaded with water in an attempt to protect the well from any possible adverse effects of the frac. These precautions were implemented due to the close proximity of the Northeast Hogback Unit #36 to the lateral portion of the Northeast hogback Unit #74H.

On the morning of April 14th, Chuza personnel performing a post-frac field inspection discovered crude oil leaking out of the Bradenhead valve and around the wellhead area of the Northeast Hogback Unit #36. A sample of the gas escaping from the Bradenhead valve was analyzed and determined to be 91.978% nitrogen, and the Bradenhead valve was observed to have a pressure reading of 105psi.

It is Chuza's belief that the hydraulic fracturing operations on the Northeast Hogback Unit #74H possibly caused a casing or cement failure on the Northeast Hogback Unit #36, which may have resulted in the pressure at the Bradenhead of the Northeast Hogback Unit #36. Chuza intends to re-test this well and either plug and abandon it or perform a remedial operation to ensure that well integrity is maintained or restored.

ACCEPTED FOR RECORD

		JUN 0 2 2014
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Patrick Padilla Title	President, Chuza Oil Compar	THE PROPERTY
Signature Date	05/18/2014	BY: 15 Sayers
THIS SPACE FOR FEDERAL	OR STATE OFFICE US	Е
Approved by		
	Title	Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office	
Tid. 10 H C C Service 1001 - 1714 42 H C C C C 1210		64 H - 4 P

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

District I 1625 N. French Drive. Phone: (575) 393-6161 Fax: (575) 393-0720 District II 811 S. First Street. Phone: (575) 748-1283 Fax: (575) 748-9720 District III 1000 Rio Brazos Road. Phone: (505) 334-6178 Fax: (505) 334-6170

1320 S. St. Francis Drive, Santa Fe, NM 87505 Phone: (505) 476-3460 Fax: (505) 476-3462

State of New Mexico Energy, Minerals & Natural Resources Department Form C-102 Revised August 1, 2011

Submit one copy to Appropriate District Office


OIL CONSERVATION DIVISION 1220 South St. Francis Drive Santa Fe, NM 87505

AMENDED R	REPORT
-----------	--------

WELL LOCATION AND ACREAGE DEDICATION PLAT

'API Number Pool Code				e	Pool Name					
31.1745-34755			32870	•	HORSESHOE GALLUP					
Property Code				⁶ Property Name				*Well Number		
	00241				NE. HOGBACK UNIT				74	
'OGRID No.				°Operator Name				*Elevation		
279508					CHUZA OIL COMPANY				5432	
¹⁰ Surface Location										
UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	Eest/West line	County	
Н	10	30N	16W		2270	NORTH	330	EAST	SAN JUAN	
¹¹ Bottom Hole Location If Different From Surface										
UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County	
Ν	10	30N	16W		207	SOUTH	2570	WEST	SAN JUAN	
200: Section 10, Unit Letters H, I, J, N, O			13 Joint or Infil)	¹⁴ Consolidation Code	¹⁵ Order No. R - 13607		DV 27'13 NS. DIV.			

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION DIST. 3



Bore Communication working copy-