



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emrds.state.nm.us/ocd/District III/3distric.htm](http://emrds.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

MAY 21 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-14-15 Operator DS Simmons API #30-045-35019

Property Name Blanco Wash Well No. 06-2 Location: Unit L Section 06 Township 36N Range 04W

Well Status (Shut-In or Producing) Initial PSI: Tubing 121 Intermediate 1 Casing 121 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>121</u>		
10 min	<u>0</u>		<u>122</u>		
15 min	<u>0</u>		<u>122</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	<u>X</u>	
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

Oil well with pumping unit. Tied to CDP

By Cady Hannah

Witness _____

lease Operator
(Position)

E-mail address _____