



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170  
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

JUN 09 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-9-15 Operator Chertoni Mid LP API #30-0 45-28793

Property Name Oshea 3 Well No. 2 Location: Unit 3 Section 3 Township 31 Range 13

Well Status(Shut-In or Producing) Initial PSI: Tubing 2 Intermediate 1/1 Casing 8 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		8		
10 min	0		8		
15 min	0		7.9		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 1/1

REMARKS:

Blew through 1/4" Valve for 30 seconds.

(Nothing after 5 min Shut-in)

By Lucinda Pacheco

Witness

Monica Kuckling

(Position)

E-mail address \_\_\_\_\_