



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://emnrd.state.nm.us/ocd/DistrictIII3distric.htm>

OIL CONS. DIV DIST. 3

JUN 22 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

DJS INC  
MAY 26 2015

Date of Test 5-14-15 Operator DS Simmons API #30-0 45-34096  
Property Name Blanco Wash Well No. 27-1 Location: Unit A Section 27 Township 8N Range 24N  
Well Status (Shut-In or Producing) Initial PSI: Tubing 157 Intermediate 1 Casing 157 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>157</u>		
10 min	<u>0</u>		<u>158</u>		
15 min	<u>0</u>		<u>157</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>X</u>
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

Oil well with pumping unit. Prod to CDP

By Cody Hannah  
Lease Operator  
(Position)

Witness \_\_\_\_\_

E-mail address \_\_\_\_\_