



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-23-15 Operator Robert L. Bayless API #30-0 45-05756

Property Name 10010 Lugo J. B. (SW) Well No. 2 Location: Unit 20 Section 20 Township 26 Range 18

Well Status (Shut-In or Producing) Initial PSI: Tubing 26 Intermediate 128 Casing 128 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		34		
10 min	0		50		
15 min	0		64		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

OIL CONS. DIV. DIST. 3
JUN 23 2015

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 128

REMARKS:

Long puff when opened. 250-300 barrels/day for both wells
78 lbs on casing after 5 min shut in
Nothing when opened after 5 min shut in

By [Signature]
(Position)

Witness [Signature]

E-mail address _____