Submit 3 Copies To Appropriate District	State of New Mexico		Form C-103
Office District I	Energy, Minerals and Natural Resources		Jun 19, 2008
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-045-09669
District III	1220 South St. Francis Dr.		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		STATE FEE S
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Salita PC, INIVI 67303		6. State Oil & Gas Lease No.
87505			FEE
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			Harvey
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			
1. Type of Well: Oil Well ☐ Gas Well ☒ Other		8. Well Number 1	
2. Name of Operator			9. OGRID Number
Burlington Resources Oil Gas Company LP			14538
3. Address of Operator			10. Pool name or Wildcat
P.O. Box 4289, Farmington, NM 87499-4289			Aztec Pictured Cliffs
4. Well Location			
Unit Letter L : 1718 feet from the South line and 923 feet from the West line			
Section 9			NMPM San Juan County
Section 9 Township 30N Range 11W NMPM San Juan County 11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
5588' GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
12. Shock repropriate Box to indicate retailed, report of Other Bata			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOR			
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRIL			LLING OPNS.□ P AND A 🛛
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ CASING/CEMENT JOB ☐			
DOWNHOLE COMMINGLE			
		·	
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion.			
5/19/15 Brandon Powell/OCD was contacted regarding results of the CBL showing TOC for plug 2 @ 487'. Rec'vd verbal			
approval to spot balanced plug.			
approval to spot obtained p	·		Oll one
The subject well was P&A'd on 5/20/15 per the above notification and the attached report. OIL CONS. DIV DIST. 3			
•	Annoved	formula and a second	
2113	Liability i	for plugging of welll inder bond is retaine	bore only. MAY 26 2015
TNR	Receipt of	C-103 (Subsequent l	a penang Report of Woll ———
Spud Date:	Plugging)	which may be found	@ OCD web
	O page unde		
I hereby certify that the information above is true and complete www.emnrd.state.us/ocd			
	P 72	7	
SIGNATURE / Mille	Musse TITLE	Staff Regulatory	Technician DATE 5/26/15
	<u>e</u> E-mail address: <u>dollie.l</u>	.busse@conocophil	lips.com PHONE: 505-324-6104
For State Use Only DEPUTY OIL & GAS INSPECTOR			
ADDROVED BY: HALL	<i>4</i> / /		7 00 12
APPROVED BY: // // // Conditions of Approval (if any):	TITLE_	PICTRI	11 #3 DATE 3-40-13
Conditions of Approval (if any):	₽V		



A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Burlington Resources **Harvey #1**

May 20, 2015 Page 1 of 1

1718' FSL and 923' FWL, Section 9, T-30-N, R-11-W San Juan County, NM Lease Number: FEE API #30-045-09669

Plug and Abandonment Report Notified NMOCD and BLM on 5/14/15

Plug and Abandonment Summary:

- **Plug #1** with 77 sxs (90.86 cf) Class B cement inside casing from 1993' to 1594' to cover the casing shoe, Point Lookout and Fruitland tops.
- **Plug #2** with 43 sxs (50.74 cf) Class B cement inside casing from 710' to 487' to cover the Kirtland and Ojo Alamo tops.
- Plug #3 with squeeze holes at 148' and CR at 96' spot 88 sxs (103.84 cf) Class B cement inside casing from 148' to surface with 59' sxs in annulus, 10 sxs below CR and 19 sxs above CR to cover the surface casing shoe. Tag TOC at 8'.
- Plug #4 with 36 sxs Class B cement top off casings and weld on P&A marker with coordinates 36° 49.463' N / 108° 00.142' W.

Plugging Work Details:

- 5/18/15 Rode rig and equipment to location. Spot in and RU. Check well pressures: no tubing, casing and bradenhead 0 PSI. RU A-Plus relief lines. ND wellhead. RU Well Check pressure valve. NU kill spool and BOP. Pressure test blind 2-3/8" pipe rams to 250 PSI and 1200 PSI, OK. Pull tubing hanger. RD Well Check. SI well. SDFD.
- 5/19/15 Bump test H2S equipment. Open up well; no pressures. Function test BOP. RU A- Plus wireline. Ran CBL from 1993' to surface, found cement at 160'. PU and tally 63 jnts 2-3/8" tubing A-Plus to 1993'. Establish circulation. Pressure test casing to 800 PSI, OK. Spot plug #1 with calculated TOC at 1594'. Establish circulation. Note: B. Powell, NMOCD approved balanced plug. Spot plug #2 with calculated TOC at 487'. RU A-Plus wireline. Perforate 4 HSC squeeze holes at 148'. Establish circulation. PU 7" DHS CR and set at 96'. Establish circulation. Spot plug #3 with TOC at surface. SI well. SDFD.
- 5/20/15 Bump test H2S equipment. Open up well; no pressures. Function test BOP. Tag TOC at 8'. Dig out wellhead. RU High Desert. Cut off wellhead. Found cement at surface in 7" casing and down 7' in annulus. Spot plug #4 top off casings and weld on P&A marker with coordinates 36° 49.463' N / 108° 00.142' W. RD and MOL.

Jim Morris, MVCI representative, was on location. John Durham, NMOCD representative, was on location.