	Submit 1 Copy To Appropriate District Office	State of New M		Form C-103	
	<u>District I</u> – (575) 393-6161 1625 N French Dr. Hobbs NM 88240	25 N. French Dr., Hobbs, NM 88240 strict II - (575) 748-1283 I S. First St., Artesia, NM 88210 strict III - (505) 334-6178 00 Rio Brazos Rd., Aztec, NM 87410 OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Sente Fe NM 87505		Revised August 1, 2011 WELL API NO.	
×	District II - (575) 748-1283			30-039-31294	
	811 S. First St., Artesia, NM 88210 District III – (505) 334-6178			5. Indicate Type of Lease	
	1000 Rio Brazos Rd., Aztec, NM 87410			STATE FEE	
	District IV – (505) 476-3460 Santa Fe, NIVI 87505		6. State Oil & Gas Lease No. E012079		
	SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		LUG BACK TO A	 Lease Name or Unit Agreement Name 132829 	
	PROPOSALS.) 1. Type of Well: Oil Well 🛛	Gas Well 🗌 Other		8. Well Number NE Chaco Com #243H	
	2. Name of Operator			9. OGRID Number	
ł	WPX Energy Production, LLC 3. Address of Operator			120782 10. Pool name or Wildcat	
	721 South Main Avenue, Aztec NM 87410			Chaco Unit NE HZ (oil)	
ł	4. Well Location				
	Unit LetterL_:1449'feet from theSOUTH line and344'feet from the WESTline				
Unit Letter I 1531' feet from the EAST line and 237' feet from the EAST line				feet from the EAST line	
	Section 16 Township 23N Range 6W NMPM County: Rio Arriba				
	11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
1	6858'				
	12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
	NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK				K 🔲 ALTERING CASING 🗌	
	TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB DOWNHOLE COMMINGLE				
	OTHER: POST SQUEEZE OTHER: ☑				
-	13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
<u>6/14/15</u> -WPX completed the WellLock squeeze.					
6/15/15-After drilling out and attempting to pressure test to 4000 psi, it was only able to reach 2500 psi which bled down to 800 psi in 5 minutes.					
<u>6/16/15</u> - performed a few additional pressure tests after circulating out our foamy water that was used to drill out the WellLock plug. We were able to establish a leak off rate of \sim 73 psi/min. This was a 4300 psi test, that lost 3300 psi in a 45 minute timeframe.					
t	With this reduction in leak off, we were unable to establish an injection rate that would allow successful placement of an additional squeeze without having to break down the formation. The well pressured out when pumping under $\sim 1/2$ bpm. Breaking down the formation could lead to lack of near wellbore placement, and therefore a much greater leak to contend with.				
Since this damage is within the production window and leak off was minimized from the initial WellLock squeeze, WPX would like to proceed forward with the frac under the assumption that the leak off is not great enough to warrant concern once other perforations are opened. This is in lieu of a secondary squeeze that would have a minimal chance of success due to current conditions and the further increased risk associated with a casing patch option.					
2/26/15					
2			ale.	OIL CONS. DIV DIST. 3	
JUN 19 20.0					
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
S	SIGNATURE				
	Type or print name Lacey Granillo_ E-mail address: _lacey.granillo@wpxenergy.com_ PHONE: _505-333-1816 For State Use Only				
_					
A	APPROVED BY: <u>1216</u> Conditions of Approval (if any):		DISTRICT #3	DATE 1/2/15	

7

ų,

6/17/15- WPX received verbal approval from NMOCD (Brandon Powell) with conditions as follows:

- Pressure test the annulus after each stage checking the leak off rate to ensure the leaking interval has not been fraced instead of the perforations.
- If it has been determined that the leaking interval has been further compromised notify the OCD with WPX's plan forward prior to proceeding.

Will follow up on completion sundry