

30-045-30156

10

OIL CONS. DIV DIST. 3

JUN 29 2015

55  
x70

4 1/2 casing  
620 psl  
6-23-15

Paul White  
6-23-15

CHART NO. MC MP-1000-IHR  
METER  
45-30156  
CHECK OF Farmington  
LOCATION M  
REMARKS  
wf Federal 21 #002  
1 line = 1 min  
6-23-15  
TAKEN OFF M

50

45

40

35



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

JUN 23 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6/23/2015 Operator XTO API #30-0 45-30156

Property Name WF Federal 21 Well No. 2 Location: Unit F Section 21 Township 30 Range 14

Well Status(Shut-In or Producing) Initial PSI: Tubing      Intermediate      Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
5 min	0	-	0		
10 min	0	-	0		
15 min	0	-	0		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR      FRESH      SALTY      SULFUR      BLACK     

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE     

REMARKS: nothing on bradenhead

By Ken Durham  
Production Foreman  
(Position)

Witness Paul Wicks

E-mail address