

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Burlington Resources Oil & Gas Company	Contact Crystal Tafoya
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9837
Facility Name: Allison Unit 129S	Facility Type: Gas Well

Surface Owner State	Mineral Owner State	API No. 3004531332
----------------------------	----------------------------	---------------------------

LOCATION OF RELEASE

Unit Letter H	Section 16	Township 32N	Range 7W	Feet from the 2200	North/South Line North	Feet from the 1065	East/West Line East	County San Juan
-------------------------	----------------------	------------------------	--------------------	------------------------------	----------------------------------	------------------------------	-------------------------------	---------------------------

Latitude **36.98428** Longitude **-1007.56657**

NATURE OF RELEASE

Type of Release Natural Gas	Volume of Release 105 MCF	Volume Recovered 0 MCF
Source of Release 1" Nipple on Compressor	Date and Hour of Occurrence 6/4/2015 at 9:00 PM	Date and Hour of Discovery 6/5/15 at 6:30AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
N/A

OIL CONS. DIV DIST. 3

JUN 10 2015



Describe Cause of Problem and Remedial Action Taken.*

1" Nipple broke on gas cooler of rental compressor. Unit went down on low discharge pressure and the well was shut-in

Describe Area Affected and Cleanup Action Taken.*

No further remediation will be taken

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Crystal Tafoya	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 7/6/15	Expiration Date:
E-mail Address: crystal.tafoya@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/8/2015 Phone: (505) 326-9837		

* Attach Additional Sheets If Necessary

#NCS 1518756757

①