Form 3160-5 (March 2012)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014

SF 077123

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS

On not use this form for proposals to drill or to re-enter an injunction Field Office

abandoned well. Use Form 3160-3	(APD) for such proposals of L	and l/lanagement
SUBMIT IN TRIPLICATE - O	ther instructions on page 2.	7. If Unit of CA/Agreement, Name and/or No.
1. Type of Well		a W ii N
Oil Well Gas Well Other		8. Well Name and No. Federal 14 #1
2. Name of Operator WEST LARGO CORP.		9. API Well No. 30-045-28461
3a. Address 8801 S. Yale Ave. Suite 240 Tulsa, OK 74137-3535	3b. Phone No. (include area code)	10. Field and Pool or Exploratory Area
	(918) 492-3239	Basin Fruitland Coal
1570' FNI 1240' FEL. Sec 14 T28N R9W NMPM		San Juan, New Mexico
12. CHECK THE APPROPRIATE	BOX(ES) TO INDICATE NATURE OF 1	NOTICE, REPORT OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF	FACTION
Notice of Intent Acidize	☐ Deepen ☐	Production (Start/Resume) Water Shut-Off
Alter Casing	Fracture Treat	Reclamation Well Integrity
Subsequent Report	New Construction	Recomplete Other
Change Plans  Final Abandonment Notice  Convert to Injecti	Plug and Abandon  on Plug Back	Temporarily Abandon  Water Disposal
		ing date of any proposed work and approximate duration thereof. If
the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)  Well failed preliminary bradenhead test. Assumed hole in 4-1/2" prod. csg. MIRU Key Energy workover rig # 31, COH w/ 2444' 1.900" tbg. MIRU BlueJet		
Logging, GIH w/ CIBP, set above perfs @ 2000'. GIH w/ 4-1/2" pkr on 2-3/8" tbg workstring. Test csg for hole, found @ 265'.  4/29/15 MIRU Halliburton Cementers. Remove BOP, NU Cmt head and manifold. Pump 12 bbls fresh wtr @ 1.2 bbl/min @ 777 psi to establish rate. Pump 24 bbls (118 sks) CI G cmt, circ to surface through open bradenhead. Close bradenhead and squeeze to 450 psi, SI wellhead.		
4/30/15 GIH w/ 4-1/2" blade bit, drill collars on 2-3/8" workstring. Tag cmt at 210'. Drill cmt to 317'. COH w/ workstring and bit.		
5/1/15 MIRU High Tech pressure truck for MIT test (witness by P. Wiebe from OCD). Press csg to 560 psi, held for 30 min with no reduction.		
5/4/15 GIH w/ 4-1/2" blade bit, drill collars on 2-3/8" workstring. Tag CIBP @ 2000'. Drilled out BP, chased remains down to csg fillup @ 2410'.		
5/5/15 MIRU High Tech air compression unit. Resume drilling BP and clean out hole to PBTD @ 2500'. COH w/ workstring, collars and bit.		
5/6/15 GIH w/ 2407' 1.900" tbg. RDMO Key Energy Rig #31. Put well back on production, initial rate @ 200 MCFD.		
14. Thereby certify that the foregoing is true and correct. Name (Pr John Patrick Garrett	inted/Typed)	Oll Assu
John Patrick Garrett	Title President	ONS. DIV DIST 3
Signature	Date 05/07/2015	OIL CONS. DIV DIST 3 MAY 18 20,3
THIS SPACE	CE FOR FEDERAL OR STATE	
Approved by		
	Title	Date
Conditions of approval, if any, are attached. Approval of this notice that the applicant holds legal or equitable title to those rights in the suentitle the applicant to conduct operations thereon.	does not warrant or certify	1000
		fully to make to any department or agency of the United States any false,  ACCEPTED FOR RECGED

(Instructions on page 2)

MAY 12 2015

