



NEW MEXICO ENERGY, MINERALS and
NATURAL RESOURCES DEPARTMENT

OIL CONS. DIV DIST. 3

JUL 23 2015

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 7-23-15 Operator Devon Energy API # 30-0 45-27340

Property Name NEBUTamp Mesa SWD Well # 1 Location: Unit ___ Sec 36 Twn 31 Rge 8

Land Type:

State ___
Federal ___
Private ___
Indian ___

Well Type:

OIL CONS. DIV DIST. 3

JUL 23 2015

Water Injection ___
Salt Water Disposal ☒
Gas Injection ___
Producing Oil/Gas ___
Pressure observation ___

Temporarily Abandoned Well (Y/N): 0 TA Expires: _____

Casing Pres. 0
Bradenhead Pres. 0
Tubing Pres. 1774
Int. Casing Pres. 0

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. _____

Pressured annulus up to 500 psi. for 30 mins. Test passed/failed

REMARKS:

fell to 470 and held for 1506 50 minute test.
Jacker set 8030

Casing opened at end of make sure well was not
flowing at zero flowed to a drip


By Aggie
(Operator Representative)

Witness Monica Kuehling
(NMOCD)

Leke Operator
(Position)

Monitor casing & tubing with chart
Monitor bh int with gauges

Revised 02-11-02



OIL CONS. DIV DIST. 3

JUL 23 2015

470 PSI
7500

Start
500 PSI



Graphic Controls

30-045 27340

CHART NO. MC MP-1000-1HR

METER 7-23-15

Ruwa Energy

CHART PUT ON
MIT TEST

TAKEN OFF

LOCATION NEbu pump mesa sud #1

REMARKS Rafael Riba
HHR #38

Monica Gubling
Dinoel
Dassiel

Casing Test
(MIT)

MIT