

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUL 31 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Burlington Resources Oil & Gas Company	Contact Crystal Walker
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9837
Facility Name: Herrin 1R	Facility Type: Gas Well
Surface Owner Private	Mineral Owner BLM (SF-080655)
API No. 30-045-20595	

LOCATION OF RELEASE

Unit Letter K	Section 13	Township 29N	Range 10W	Feet from the 1850	North/South Line South	Feet from the 1850	East/West Line West	County San Juan
-------------------------	----------------------	------------------------	---------------------	------------------------------	----------------------------------	------------------------------	-------------------------------	---------------------------

Latitude 36.72313 Longitude -107.83852

NATURE OF RELEASE

Type of Release Natural Gas	Volume of Release 82 mcf	Volume Recovered 0 mcf
Source of Release Valve	Date and Hour of Occurrence 7/7/2015 at 2:00PM	Date and Hour of Discovery 7/8/15 at 9:45AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
N/A



Describe Cause of Problem and Remedial Action Taken.*

High winds blew over a meter house breaking off a 1/4" blow down valve for the meter at the threads allowing 82mcf of Pictured Cliff gas to be released to the atmosphere. The well was immediately shut-in and repaired.

Describe Area Affected and Cleanup Action Taken.*

No further remedial action will be performed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Crystal Walker	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 8/12/15	Expiration Date:
E-mail Address: crystal.walker@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7/29/15 Phone: (505) 326-9837		

* Attach Additional Sheets If Necessary

#NCS 1522436302