



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-13-15 Operator Burlington API #30-0 45 20936
Property Name ERNG A Well No. 1 Location: Unit 21 Township 32 Range 6
Well Status (Shut-In or Producing) Initial PSI: Tubing 164 Intermediate 0 Casing 168 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	169	0	169
10 min	0	0	169	0	169
15 min	0	0	169	0	169
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		✓
Nothing	✓	
Gas		✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

Seal fixed on well head.

BH nothing when opened.

Int. long puff when opened. cleared at 6 seconds

By Dennis Smith

Witness Monica Kuhlman

MSO Run 410

(Position)

BH & Int nothing when opened
after 5 min shut-in.
Request Dennis on what was
fixed on well

E-mail address _____

OIL CONS. DIV. DIST. 3
AUG 13 2015