

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

JUL 31 2015

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company NM&O OPERATING COMPANY	Contact CAUY DAVIS or LARRY SWEET
Address 15 EAST 5 <sup>TH</sup> STREET STE 3000 TULSA OK 74103	Telephone No. 5053206502 9185843802
Facility Name RUCKER LAKE No. 2 SWD	Facility Type SALT WATER DISPOSAL
Surface Owner Larry Hatley	Mineral Owner NM&O OPERATING CO. API No. 30-039-23231

#### LOCATION OF RELEASE



Unit Letter K	Section 24	Township 25N	Range 2W	Feet from the 1450	North/South Line SOUTH	Feet from the 1520	East/West Line WEST	County RIO ARRIBA
------------------	---------------	-----------------	-------------	-----------------------	---------------------------	-----------------------	------------------------	----------------------

Latitude 36.3801422 Longitude 107.0053711

#### NATURE OF RELEASE

Type of Release Oil/Condensate	Volume of Release <u>80</u>	Volume Recovered <u>40</u>
Source of Release Tank	Date and Hour of Occurrence: 4/14/13	Date and Hour of Discovery: 4/15/13
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD and Larry Sweet	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* TANK BOTTOM RUSTED THROUGH. MOSTLY CLEANED 2 YEARS PRIOR EXCEPT DIRECTLY UNDER THE TANK. PERMISSION GRANTED FROM OCD TO COMPLETE ONCE THE TANK WAS REMOVED.		
Describe Area Affected and Cleanup Action Taken.*DIRECTLY UNDER TANK. CLEANUP TO COMMENCE		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Gerri Shipley	Approved by Environmental Specialist: 	
Title: Contractor	Approval Date: <u>8/18/15</u>	Expiration Date:
E-mail Address: gerrishipley@gmail.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7/27/15 Phone: 5053203229		

\* Attach Additional Sheets If Necessary

#NCS 15 230 325 30