

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

AUG 24 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ConocoPhillips Company	Contact Lindsay Dumas
Address 3401 East 30 th St, Farmington, NM	Telephone No.(505) 258-1643
Facility Name: San Juan 28-7 261M	Facility Type: Gas
Surface Owner BLM	Mineral Owner SF-078496
API No. 30-039-26540	

LOCATION OF RELEASE

Unit Letter F	Section 05	Township 27N	Range 07W	Feet from the 1510'	North/South Line FNL	Feet from the 1475'	East/West Line FWL	County Rio Arriba
-------------------------	----------------------	------------------------	---------------------	-------------------------------	--------------------------------	-------------------------------	------------------------------	-----------------------------

Latitude 36.606612 Longitude -107.59988

NATURE OF RELEASE

Type of Release Hydrocarbon and produced water	Volume of Release 115.8 bbls HC/8.9 bbls PW	Volume Recovered 11.8 bbls HC
Source of Release Production tank drain line	Date and Hour of Occurrence unknown	Date and Hour of Discovery 8/18/2015 @11:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Cory Smith and Shari Ketcham	
By Whom? Lindsay Dumas	Date and Hour 8/19/2015 7 AM phone call/ 3 pm email	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A vandal opened the drain valve and moved the drain line from dumping into the pit to dumping into cribbing; releasing 124.7 total bbls of hydrocarbon and produced water into the cribbing.

Describe Area Affected and Cleanup Action Taken.*

ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Lindsay Dumas	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 9/2/15	Expiration Date:
E-mail Address: Lindsay.Dumas@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/21/2015	Phone: (505) 258-1643	

* Attach Additional Sheets If Necessary

#NCS 15245 40 525