

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

AUG 24 2015

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office to  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

## OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ConocoPhillips Company	Contact Lindsay Dumas
Address 3401 East 30 <sup>th</sup> St, Farmington, NM	Telephone No. (505) 258-1643
Facility Name: San Juan 28-7 244M	Facility Type: Gas

Surface Owner BLM	Mineral Owner NMSF-078835-A	API No. 30-039-26873
-------------------	-----------------------------	----------------------

## LOCATION OF RELEASE

Unit Letter <b>D</b>	Section <b>07</b>	Township <b>27N</b>	Range <b>07W</b>	Feet from the <b>850'</b>	North/South Line <b>FNL</b>	Feet from the <b>965'</b>	East/West Line <b>FWL</b>	County <b>Rio Arriba</b>
-------------------------	----------------------	------------------------	---------------------	------------------------------	--------------------------------	------------------------------	------------------------------	-----------------------------

Latitude 36.5932 Longitude -107.62078

## NATURE OF RELEASE

Type of Release Hydrocarbon and produced water	Volume of Release 13 bbls HC/7bbls PW	Volume Recovered 0 bbls
Source of Release production tank drain line	Date and Hour of Occurrence <b>unknown</b>	Date and Hour of Discovery <b>8/11/2015 @12 pm</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Cory Smith and Shari Ketcham</b>	
By Whom? Lindsay Dumas	Date and Hour 8/11/2015 @3:30pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A vandal opened the drain valve and moved the drain line from dumping into the pit to dumping on the ground; releasing 20 total bbls of hydrocarbons and produced water on to the ground.

Describe Area Affected and Cleanup Action Taken.\*

ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Lindsay Dumas</i>	OIL CONSERVATION DIVISION	
Printed Name: Lindsay Dumas	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Environmental Specialist	Approval Date: <i>9/2/15</i>	Expiration Date:
E-mail Address: Lindsay.Dumas@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/21/2015	Phone: (505) 258-1643	

\* Attach Additional Sheets If Necessary

#NCS 1524540741