

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

OIL CONS. DIV DIST. 3

AUG 24 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	ConocoPhillips Company	Contact	Lindsay Dumas
Address	3401 East 30 th St, Farmington, NM	Telephone No.	(505) 258-1643
Facility Name	San Juan 28-7 145F	Facility Type	Gas

Surface Owner	BLM	Mineral Owner	SF-078972	API No.	30-039-27078
---------------	-----	---------------	-----------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	10	27N	07W	1835'	FNL	1810'	FWL	Rio Arriba

Latitude 36.59074 Longitude -107.56396

NATURE OF RELEASE

Type of Release	Hydrocarbons and produced water	Volume of Release	38 bbls HC/ 23 bbls PW	Volume Recovered	0 bbls
Source of Release	Production tank drain line	Date and Hour of Occurrence	unknown	Date and Hour of Discovery	8/6/2015
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Cory Smith and Shari Ketcham		
By Whom?	Lindsay Dumas	Date and Hour	8/6/2015 @ 12:30 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A vandal opened the drain valve and moved the drain line from dumping into the pit to dumping into the cribbing; releasing 61 total bbls of condensate and produced water into cribbing.

Describe Area Affected and Cleanup Action Taken.*

ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Lindsay Dumas	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 9/2/15	Expiration Date:
E-mail Address: Lindsay.Dumas@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/21/2015	Phone: (505) 258-1643	

* Attach Additional Sheets If Necessary

#NCS 15245 41028