



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 8/18/2015 Operator Western Minerals & Oil API # 45-21835

Property Name Marron Well No. 6A Location: Unit C Section 24 Township 27N Range 8W

Well Status (Shut-In or Producing) Tubing 20 Intermediate --- Casing 260 Bradenhead 17

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>	<u>---</u>	<u>260</u>	Steady Flow <u>---</u>	
10 minutes	<u>0</u>	<u>---</u>	<u>260</u>	Surges <u>---</u>	
15 minutes	<u>0</u>	<u>---</u>	<u>259</u>	Down to Nothing <u>X</u>	
20 minutes	<u>0</u>	<u>---</u>	<u>260</u>	Nothing <u>---</u>	
25 minutes	<u>0</u>	<u>---</u>	<u>260</u>	Gas <u>---</u>	
30 minutes	<u>0</u>	<u>---</u>	<u>259</u>	Gas & Water <u>---</u>	
				Water <u>---</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR --- FRESH --- SALTY --- SULFUR --- BLACK ---

OIL CONS. DIV DIST. 3

SEP 03 2015

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE ---

REMARKS: Blew down to nothing in 15 seconds

By Bob Cherault
Pumper
(Position)

Witness Steven Gallegos

E-mail address bob@ccunm.com