

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3dlistric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-14-2015 Operator Western Minerals & Oil API # 45-21316	
Property Name Marron Well No. 5 Location: Unit H Section 27 Township 27N Range 8W	
Well Status(Shut-In or Producing) Initial PSI: Tubing 26 Intermediate Casing 44 Bradenhead 0	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
BH Int Csg Int Csg	
TIME 5 min 6 - 44	Steady Flow
10 min 0 - 45	Surges
15 min 0 - 44	Down to Nothing
20 min — 44	Nothing
25 min — 45	Gas
30 min 44	Gas & Water
	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY	SULFURBLACK
5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE INTERMEDIATE	
REMARKS: Bondonband had 4 Pot an it had	
blew down to nothing in 10 seconds	
By Bob Chenault Witness Steven Gallegos	
Pumper (Position)	
E-mail address Bob@ccinm.com	