



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

SEP 09 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-25-2015 Operator MARLEX RES. INC. API #30-0 45-29208

Property Name TRADING POST Well No. 1 Location: Unit _____ Section _____ Township _____ Range _____

Well Status (Shut-In or Producing) Initial PSI: Tubing 35 Intermediate _____ Casing 30 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min			30		
10 min			30		
15 min			30		
20 min			30		
25 min			30		
30 min			30		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	Ø	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Ø

INTERMEDIATE _____

REMARKS:

By BOB SPENCER

Witness John Dorfman

PUMPER
(Position)

E-mail address maralex-tech@gmail.com