Form 3160-5 (August 2007)	UNITED STAT DEPARTMENT OF THI BUREAU OF LAND MA	E INTERIOR	AUG 2	5. Lease Serial No.	No. 1004-0137 s: July 31, 2010
Do not us	NDRY NOTICES AND REP e this form for proposals well. Use Form 3160-3 (/	to drill or to regen	ter an 👘	6 <sup>1</sup> If Indian, Allöttee or Tribe	EE LEASE Name NM 73316
	JBMIT IN TRIPLICATE - Other in:	structions on page 2.		7. If Unit of CA/Agreement,	
1. Type of Well	X Gas Well Other			8. Well Name and No.	nt 5-11-54 #14-08-001-1690
					senberry 2A
2. Name of Operator	stop Popouroos Oil & Cos	Company I P		9. API Well No.	045 21912
3a. Address	iton Resources Oil & Gas	3b. Phone No. (include:	area code)	10. Field and Pool or Explore	-045-21813
PO Box 4289, Farmingt	on, NM 87499	(505) 326-		-	co Mesaverde
4. Location of Well (Footage, Sec., T., I Surface Unit G (S	R.,M., or Survey Description) WNE), 1620' FNL & 1590'	FEL, Sec. 1, T31N	, R12W	11. Country or Parish, State San Juan	, New Mexico
12. CHECK	THE APPROPRIATE BOX(ES	) TO INDICATE NAT	URE OF NO	TICE, REPORT OR OTH	HER DATA
TYPE OF SUBMISSION			YPE OF AC		
X Notice of Intent	Acidize	Deepen		roduction (Start/Resume)	Water Shut-Off
	Alter Casing	Fracture Treat		eclamation	Well Integrity
Subsequent Report	Casing Repair	New Construction	R	ecomplete	X Other
Final Abandonment Notice	Change Plans	Plug and Abandon Plug Back		emporarily Abandon /ater Disposal	FAN
•	P&A'd on 4/13/10. Reclar 16/11. <del>Burlington-Resour</del>			<del>rwell be removed fr</del> OIL C(	
<ol> <li>14. 1 hereby certify that the foregoing is</li> <li>Do</li> </ol>	s true and correct. Name (Printed/Typ Ilie L. Busse	ped) Title		Staff Regulatory To	echnician
Signature Milie	Busse		<u> 3-19-1</u>		
	THIS SPACE FO	OR FEDERAL OR	STATE OFF	ICE USECCEPTED PO	R RFMMM.
Approved by Conditions of approval, if any, are attac that the applicant holds legal or equitab entitle the applicant to conduct operatio	le title to those rights in the subject le ms thereon.	ase which would	Title Office	AIIG Ü G FARMINGTON FIE BY:	
Title 18 U.S.C. Section 1001 and Title false, fictitious or fraudulent statements			gly and willfully	to make to any department or	agency of the United States any
(Instruction on page 2)	M	NOCO			

•

Office	State of New Me		Form C-103
District I	Energy, Minerals and Natu	iral Resources	Jun 19, 2008
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION	I DIVISION	30-045-21813 5. Indicate Type of Lease
District III	1220 South St. Fran	ncis Dr.	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 8	7505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM			
87505 ·	CES AND REPORTS ON WELLS		7 Loogo Nome or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPO	ICES AND REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PL CATION FOR PERMIT" (FORM C-101) FO	UG BACK TO A	7. Lease Name or Unit Agreement Name Dusenberry
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other OIL CONS		8. Well Number 2A
~			9. OGRID Number
Burlington Resources Oil Gas C	ompany LP SEP 6	2 3 2015	14538
3. Address of Operator P.O. Box 4289, Farmington, NM 8		9 8 201J	Blanco Mesaverde
			Bianco mesaveroc
4. Well Location		1) <u> </u>	
Unit Letter <u>G</u> : 162		line and159	
Section 1		inge 12W	NMPM San Juan County
	11. Elevation (Show whether DR		
	6336		
12. Check A	Appropriate Box to Indicate N	ature of Notice,	Report or Other Data
NOTICE OF IN		SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK		REMEDIAL WOR	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR	
PULL OR ALTER CASING		CASING/CEMEN	
			OIL CONS. DIV.
	· · □		
All pits have been remediated i	n compliance with OCD rules and t	he terms of the Ope	
<ul> <li>Rat hole and cellar have been fix</li> <li>A steel marker at least 4" in dia</li> <li>OPERATOR NAME, LE</li> <li>UNIT LETTER, SECTION</li> <li>PERMANENTLY STAM</li> <li>The location has been leveled a other production equipment.</li> <li>Anchors, dead men, tie downs a other production equipment.</li> <li>If this is a one-well lease or lass OCD rules and the terms of the removed from lease and well low</li> <li>All metal bolts and other mater have to be removed.)</li> </ul>	n compliance with OCD rules and t illed and leveled. Cathodic protecti uneter and at least 4' above ground ASE NAME, WELL NUMBER, DN, TOWNSHIP, AND RANGE. IPED ON THE MARKERS SUR is nearly as possible to original grou and risers have been cut off at least t remaining well on lease, the batter operator's pit permit and closure po cation. ials have been removed. Portable b een abandoned in accordance with	he terms of the Ope ion holes have been level has been set in <u>API NUMBER, OI</u> <u>ALL INFORMAT</u> <u>FACE.</u> and contour and has two feet below grou- y and pit location(s plan. All flow lines bases have been rem	erator's pit permit and closure plan. properly abandoned. n concrete. It show the UARTER/QUARTER LOCATION OR FION HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and
<ul> <li>All pits have been remediated i</li> <li>Rat hole and cellar have been fix</li> <li>A steel marker at least 4" in dia</li> <li>OPERATOR NAME, LE</li> <li>UNIT LETTER, SECTIO</li> <li>PERMANENTLY STAM</li> <li>The location has been leveled a other production equipment.</li> <li>Anchors, dead men, tie downs a other removed from lease and well low of the removed from lease and well low All metal bolts and other mater have to be removed.)</li> <li>Pipelines and flow lines have b retrieved flow lines and pipelin</li> </ul>	n compliance with OCD rules and t illed and leveled. Cathodic protecti uneter and at least 4' above ground ASE NAME, WELL NUMBER, J DN, TOWNSHIP, AND RANGE. IPED ON THE MARKERS SUR is nearly as possible to original grou and risers have been cut off at least t remaining well on lease, the batter operator's pit permit and closure potention. ials have been removed. Portable be een abandoned in accordance with tes.	he terms of the Ope ion holes have been level has been set in <u>API NUMBER, QI</u> <u>ALL INFORMAT</u> <u>FACE.</u> and contour and has two feet below grou y and pit location(s plan. All flow lines bases have been rem 19.15.35.10 NMAC	erator's pit permit and closure plan. properly abandoned. n concrete. It show the UARTER/QUARTER LOCATION OR TON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and und level. ) have been remediated in compliance with , production equipment and junk have been noved. (Poured onsite concrete bases do not 2. All fluids have been removed from non-
<ul> <li>All pits have been remediated i</li> <li>Rat hole and cellar have been fix</li> <li>A steel marker at least 4" in dia</li> <li>OPERATOR NAME, LE</li> <li>UNIT LETTER, SECTIO</li> <li>PERMANENTLY STAM</li> <li>The location has been leveled a other production equipment.</li> <li>Anchors, dead men, tie downs a lf this is a one-well lease or lass OCD rules and the terms of the removed from lease and well low</li> <li>All metal bolts and other mater have to be removed.)</li> <li>Pipelines and flow lines have b retrieved flow lines and pipeling</li> <li>When all work has been completed,</li> </ul>	n compliance with OCD rules and t illed and leveled. Cathodic protecti imeter and at least 4' above ground ASE NAME, WELL NUMBER, DN, TOWNSHIP, AND RANGE. (PED ON THE MARKERS SUR) is nearly as possible to original grou and risers have been cut off at least t remaining well on lease, the batter operator's pit permit and closure pocation. ials have been removed. Portable b een abandoned in accordance with tes. return this form to the appropriate	he terms of the Ope on holes have been level has been set in <u>API NUMBER, QI</u> <u>ALL INFORMAT</u> <u>FACE.</u> and contour and has two feet below grou- y and pit location(s plan. All flow lines bases have been rem 19.15.35.10 NMAC District office to sel <u>Staff Regulator</u>	erator's pit permit and closure plan. properly abandoned. In concrete. It show the UARTER/QUARTER LOCATION OR FION HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and und level. ) have been remediated in compliance with , production equipment and junk have been tooved. (Poured onsite concrete bases do not 2. All fluids have been removed from non- hedule an inspection.
<ul> <li>All pits have been remediated i</li> <li>Rat hole and cellar have been fix</li> <li>A steel marker at least 4" in dia</li> <li>OPERATOR NAME, LE</li> <li>UNIT LETTER, SECTIO</li> <li>PERMANENTLY STAM</li> <li>The location has been leveled a other production equipment.</li> <li>Anchors, dead men, tie downs a</li> <li>If this is a one-well lease or last OCD rules and the terms of the removed from lease and well lo</li> <li>All metal bolts and other mater have to be removed.)</li> <li>Pipelines and flow lines have b retrieved flow lines and pipelin</li> <li>When all work has been completed,</li> </ul>	n compliance with OCD rules and t illed and leveled. Cathodic protecti imeter and at least 4' above ground ASE NAME, WELL NUMBER, DN, TOWNSHIP, AND RANGE. (PED ON THE MARKERS SUR) is nearly as possible to original grou and risers have been cut off at least t remaining well on lease, the batter operator's pit permit and closure pocation. ials have been removed. Portable b een abandoned in accordance with tes. return this form to the appropriate	he terms of the Ope on holes have been level has been set in <u>API NUMBER, QI</u> <u>ALL INFORMAT</u> <u>FACE.</u> and contour and has two feet below grou- y and pit location(s plan. All flow lines bases have been rem 19.15.35.10 NMAC District office to sel <u>Staff Regulator</u>	erator's pit permit and closure plan. properly abandoned. In concrete. It show the UARTER/QUARTER LOCATION OR TION HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and und level. ) have been remediated in compliance with , production equipment and junk have been woved. (Poured onsite concrete bases do not c. All fluids have been removed from non- hedule an inspection.

· .