## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	Sundry Not	ices and Reports on Well	S	
			5.	Lease Number SF-080430-A
Type of	Well	2865	NUV 3 AM <b>61</b> 0	If Indian, All. or Tribe Name
GAD			RECEIVED	111De Name
		67	O FARMENA 7.	Unit Agreement Name
	Operator			Unit Agreement Name San Juan 28-6 Unit
	<u>. NGTON</u>			
RES	OURCES OIL & GA	S COMPANY		
			8.	Well Name & Number
	& Phone No. of Opera			San Juan 28-6 Unit #
PO Box	4289, Farmington, NM	87499 (505) 326-9700	9.	
Tamatia	- of Well Weeksee G	or M D W	10	30-039-29458 Field and Pool
	n of Well, Footage, S	ec., T, K, M ec. 31, T28N, R06W, NMPM		Blanco MV/Basin DK
OHIC K	1043 FBH, 2013 FWH, B	ec. 31, 120N, ROOW, NAIP		County and State
	•			Rio Arriba, NM
			·	
		DICATE NATURE OF NOTICE,		DATA
Type of	Submission	Type of Act		
	Notice of Intent	Abandonment Recompletion	_ Change of Pl _ New Construc	ans tion
х	Subsequent Report	Plugging Back	_ New Constitut Non-Routine	Fracturing
_ <del></del>	zampodamio nobolo	Casing Repair	Water Shut o	
	Final Abandonment	Altering Casing		
		X Other - 7" Remedia	ition	7371871
10.5				2 13 14 15 /6 /
13.Desc	ribe Proposed or Comp	oleted Operations		
0/4/05 Verba	al approval received from Adrie	nne Brumley, BLM, from home to s	aneeze & remediate	NOV 2005 RECEIVED OIL CONS. DIV.
terwards).	a approvar received from Auric	mic Brumiey, BEW, Hom nome to s	queeze & remediate	RECEIVED
tor wards).				6 OIL CONS. DIV.
)/1/05 MIRU	J. RU W/L. Cut 4 1/3" casing @	2532'. TOOH w/4 ½" csg above o	ent	DIST. 3
0/5/05 RD cs	g tools. RU BWWC. Run CB	Lin 7" csg. TOC @ 2180'. Perf one	e saueeze hole @ 210	0'. Circ Mole.
0/6/05 TIH. s	set nkr @ 1909'. PT the to 200	L in 7" csg, TOC @ 2180'. Perf one 0#. Pump 24 bbls slurry w/full cmt , flush 2 bbls below pkr.	returns. Well bridged	off. Pump 32>
ols slurry w/n	o returns. Pump 5 bbls tail cmt	flush 2 bbls below pkr.		S S S S S S S S S S S S S S S S S S S
)/7/05 TOOF	H w/pkr. RU Blue Jet, run CBL	TOC @ 1700'. Perf one squeeze l	hole @ 1100'. Circ h	ole. TIH w/pkr.
et pkr @ 909	'. PT to 3500 psi. PT backside	to 500 psi. Cmt 7" csg w/54 bbls c	mt. Circ 16 bbls to su	ırface.
		it @ 1926'. Drill cmt from 1926'-19		
		o 500 psi. OK. TOH w/ bit. Blow		
	•	•		
<del> </del>				
4. I he	reby certify that the	foregoing is true and o	correct.	•
igned	Som (Vay	Title Regulatory	, Specialist Da	te 11/1/05
rgireu	The Care	Title Regulatory	Specialist Da	ice 11/1/05
This spac	e for Federal or Stat	e Office use)	<u></u>	
PPROVED B	Υ	Title	Date _	ACCEPTA
NOITION	OF APPROVAL, if any:			ACCEPTED FOR RECORD
tre 18 U.S.C. S ited States any	rection 1001, makes it a crime for a false, fictitious or fraudulent s	any person knowingly and willfully to ma tatements or representations as to any m	ke to any department or atter within its jurisdi	agency of the
		_		140 4 9 STUE
				FARMINGTON FIELD OFFICE
				· ·