Deviation Report Name of Company **Address** P.O. Box 4289, Farmington, NM 87499 Burlington Resources Oil & Gas Company Location Lease Name and Number (API Number) Sec. Twn. Rge. TRAIL CANYON #101S (30-045-33098) 08-032N-008W -1855 FSL -1570 FWL **Pool and Formation County** State **BASIN FRUITLAND COAL** SAN JUAN **NEW MEXICO**

(OH)

Depth (ft)	Deviation (degrees)	
60	0.75	
120	1.00	
620	0.50	
1,186	1.50	
1,601	0.50	
2,099	1.00	
2,602	1.00	
3,099	0.50	
3,599	1.50	
3,750	1.00	

Air Hammer Used? YES NO

I, the undersigned, certify that I, acting in my capacity as Petroleum Engineer for Burlington Resources Oil & Gas Company, am authorized by said Company to make this report; and that this report was prepared under my supervision and directions, and that the facts stated herein are true to the best of my knowledge and belief.

Subscribed and sworn to before me this 15th day of NOVEMBER, 2005.

Notary Public in and for San Juan County, New Mexico

My commission expires April 5th, 2009.





	S/T # Angle Azimuth	Legal Well Name: Common Well Name: Event Name: Contractor Name: AZTEC WELL SERVICE Rig Name: TMD: TMD: TTRAIL CANYON #101S TRAIL CANYON #101S
	CTM TVD 3 N.S	BURLINGTON RESOUR Deviation S 18 18 CE
	E-W Section DLS	AS - SJD 30/2005 7/2005 //14/2005 //15/2005 21 nod: Minimum Curvature
Printed: 11.	BUR	
Printed: 11/15/2005 3:18:16 PM	Туре	Page 1 of 1 V.S.AZI(°) 0.00