

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178

FAX: (505) 334-6170 www.emnrd.state.nm.us/ocd/District 3/district3.htm

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of T	est9-2	19-05 C	perator <u>6</u> .	ent Western Dr. 1	1. API #30-0 <u>45 -</u>	27424
Property Name Polico State Com Well No. 3 Location: Unit 5 Section 36 Township 31 Range 11						
Well Status (Shut-In or Producing) Tubing 149 Intermediate Casing Bradenhead O						
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
TIME		PRESSURES: INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes_	<u>ا</u>	<u>ک</u>	0	Steady Flow		
10 minutes	<u>٥</u>	<u>٥</u>	0	Surges		
15 minutes	0	0	0	Down to Nothin	g	
20 minutes	<u> </u>	0	<u>O</u>	Nothing	X	
25 minutes	0	<u>ට</u>	0	Gas		
30 minutes	<u>O.</u>	<u>ට</u>	0	Gas & Water		
				Water		
If bradenhead flowed water, check all of the descriptions that apply below:						
CLEAR FRESH SALTY SULFUR BLACK BLACK SULFUR SULFUR BLACK SULFUR						
5 MINUTE SHUT-IN BRADENHEAD O INTERMEDIATE OF THE SHUT-IN BRADENHEAD O						
REMARKS: Blanco - Pictured Cliffs Cull 6819						
					434	567
						250
			-			DEC 2008
By Cia	llan Ke			Witness		CEIVED SI OWS. DW.
(I	Switcher Position)				WELLE.	SISOR BLANDER
E-mail address cultan @ walsh eng. net						