

Deviation Report

Name of Company Burlington Resources Oil & Gas Company	Address P.O. Box 4289, Farmington, NM 87499	
Lease Name and Number (API Number) DUSENBERRY #2B (30-045-33210)	Location -855 FSL 480 FEL	Sec. Twn. Rge. 01-031N-012W
Pool and Formation MESAVERDE	County SAN JUAN	State NEW MEXICO

(OH)


<u>Depth (ft)</u>	<u>Deviation (degrees)</u>
100	1.00
220	1.25
320	2.00
581	1.00
835	0.75
1,083	1.00
1,333	0.75
1,581	1.00
1,835	1.00
2,335	1.25
2,835	0.75
3,305	0.25
3,805	0.25
4,305	0.25
4,796	1.00
5,274	1.75
5,650	2.00

Air Hammer Used? YES / NO

I, the undersigned, certify that I, acting in my capacity as Petroleum Engineer for Burlington Resources Oil & Gas Company, am authorized by said Company to make this report; and that this report was prepared under my supervision and directions, and that the facts stated herein are true to the best of my knowledge and belief.



Subscribed and sworn to before me this 17th day of February, 2006.



Notary Public in and for San Juan County, New Mexico

My commission expires September 15, 2008.

