

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

OIL CONS. DIV DIST. 3

SEP 22 2015

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BP	Contact: Steve Moskal	
Address: 200 Energy Court, Farmington, NM 87401	Telephone No.: 505-326-9497	
Facility Name: Mudge B 12R	Facility Type: Natural gas well	
Surface Owner: Federal	Mineral Owner: Federal	API No. 3004510792

LOCATION OF RELEASE

Unit Letter A	Section 17	Township 31N	Range 11W	Feet from the 995	North/South Line North	Feet from the 1,065	East/West Line East	County: San Juan
------------------	---------------	-----------------	--------------	----------------------	---------------------------	------------------------	------------------------	------------------

Latitude 36.902812° Longitude -108.008145°

NATURE OF RELEASE



Type of Release: Historic Production Pit	Volume of Release: unknown	Volume Recovered: none
Source of Release: Discovery of historic production pit during BGT removal.	Date and Hour of Occurrence: unknown	Date and Hour of Discovery: September 4, 2015, 8:30AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* During removal of BGT for upgrade, construction crew reported evidence of impacted soils below the BGT. The BGT and associated piping appeared to be in good, working condition. Further assessment found impacts of TPH and xylenes above remediation standards at 13' below ground surface.

Describe Area Affected and Cleanup Action Taken.\* Appears the BGT was situated above a historic production pit. The extents of impacts are not known at this time. BP plans to further delineate the area and remove impacted soils following the NMOCD soil remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Steve Moskal	Approved by Environmental Specialist: 	
Title: Field Environmental Coordinator	Approval Date: <u>10/14/15</u>	Expiration Date:
E-mail Address: steven.moskal@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: September 18, 2015	Phone: 505-326-9497	

\* Attach Additional Sheets If Necessary

#NCS1528741396