

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

OIL CONS. DIV DIST. 3

OCT 05 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BP	Contact: Steve Moskal	
Address: 200 Energy Court, Farmington, NM 87401	Telephone No.: 505-326-9497	
Facility Name: Cedar Hill 10" Pipeline - Valentine GC 1M	Facility Type: Natural gas well	
Surface Owner: State	Mineral Owner: State	API No. 3004533218

LOCATION OF RELEASE

Unit Letter C	Section 32	Township 32N	Range 10W	Feet from the 650	North/South Line North	Feet from the 1,600	East/West Line East	County: San Juan
------------------	---------------	-----------------	--------------	----------------------	---------------------------	------------------------	------------------------	------------------

Latitude 36.947100° Longitude -108.906628°

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: unknown	Volume Recovered: none
Source of Release: Pipeline corrosion	Date and Hour of Occurrence: unknown	Date and Hour of Discovery: 9/2/15; 3:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Cory Smith	
By Whom? Steve Moskal; BP	Date and Hour: 9/3/15; 4:25 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Release occurred in an erosional feature of a tributary of Cox Canyon wash. Contents not believed to reach the water course.

Describe Cause of Problem and Remedial Action Taken.* Engineer found release during field work assessment of pipeline integrity management project. Engineer reported to operations team. Pipeline was shut in pending repairs and remediation.

Describe Area Affected and Cleanup Action Taken.* BP will excavate the pipeline for repairs and perform a remediation assessment at that time. Soils samples will be collected to determine extent of required remediation following the spill guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Steve Moskal		
Title: Field Environmental Coordinator	Approval Date: <u>10/14/15</u>	Expiration Date:
E-mail Address: steven.moskal@bp.com	Conditions of Approval: <u>Test For BTEX, TPH, 3 chlorides</u>	Attached <input type="checkbox"/>
Date: September 29, 2015	Phone: 505-326-9497	

* Attach Additional Sheets If Necessary

#NCS 15287 30054

New Mexico State Land Office

Rights of Way Division

(505) 827-5842 P.O. Box 1148 Santa Fe, NM 87504



RIGHT OF ENTRY (ROE) REQUEST FOR REMEDIATION

Company Name BP America Production Company
Address 200 Energy Ct
City, State, Zip Farmington, NM 87401
Contact Person: Steve Moskal
Telephone #: (505) 326-9497
Email: steven.moskal@bp.com

Purpose of request: Access of State lands for pipeline repairs, potential remediation and erosion control

Section 32 Township 32 Range 10 Unit Letter C

Qtr/Qtr NE/NW County San Juan

GPS Location (decimal degrees): Latitude 36.947100° W Longitude -107.906628° N

If this is a remediation for a spill please attach a copy of the OCD C-141 form.

Is the completed C-141 attached? Yes ☒ No ☐

Square footage of spill impacted surface: 100

Estimated square footage of total disturbance: 4,300

Reclamation Plan (*attach addl. sheet if necessary*) Excavate pipeline and perform repairs.

Excavate and remove impacted soils. Backfill with imported clean material.

Driving directions from nearest state highway or road (*attach a map of the location*):

From the intersection of US 550 & SJ CR 2900, head north 0.7 miles, turn west. Travel 2.0 miles, turn south. Travel 1.0 miles, turn east. Travel 0.5 miles, turn south. Travel 0.25 miles. Location 150' off road to SE.

Lease number associated with the ROE request: API# 3004533128

Well Name and/or Operator (if applicable): BP America Production Company, Enterprise Products

Time expected to complete remediation: 10/30/2015

Personnel present on State Land BP, Crossfire, Enterprise

Equipment & materials present on State Land Vac-trucks, trackhoes, frontend loaders, dump truc

\$530.00 application fee (based on 180 days) can be renewed for up to 1 year.

Payable to: The Commissioner of Public Lands
P. O. Box 1148
Santa Fe, NM 87504-1148

** When you provide a check as payment, you authorize the State of New Mexico to either use information from your check to make a one-time electronic fund transfer from your account or to process the payment as a check transaction.*

Revised 09/09/2015