



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

OCT 14 2015

Date of Test 8/20/15 Operator BP America Production Company API # 3004511739

Property Name GCU 240-DK Location: Unit K Section 24 Township 28 Range 13
(Well Name and Number)

Pressure (Shut-in or ~~Producing~~) Tubing SS Intermediate - Casing SS Bradenhead SS

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor	Flowed	Flowed
5 minutes	0	-	S		S	Steady Flow	
10 minutes	0	-				Surges	
15 minutes	0	-				Down to Nothing	✓
20 minutes						No Flow	
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI	0	-				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate -

REMARKS:

Blow down from 1" valve. BH had a puff
down to nothing. Unable to get casing reading

By

[Signature]

Witness

(Position)