



# NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

## BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

OIL CONS. DIV DIST. 3

OCT 14 2015

Date of Test 8/29/15 Operator BP America Production Company API # 3004526269

Property Name GCU 237E-DK Location: Unit C Section 13 Township 28 Range 13  
(Well Name and Number)

Pressure (Shut-in or Producing) ✓ Tubing 47 Intermediate — Casing 47 Bradenhead 69

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor	Flowed	Flowed
5 minutes	<u>0</u>	<u>47</u>				Steady Flow	
10 minutes	<u>0</u>	<u>47</u>				Surges	
15 minutes	<u>0</u>	<u>47</u>				Down to Nothing	<input checked="" type="checkbox"/>
20 minutes						No Flow	
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI	<u>1</u>	<u>47</u>				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear ☐ Fresh ☐ Salty ☐ Sulfur ☐ Black ☐

5 Minute Shut-in Bradenhead 1 Intermediate —

### REMARKS:

Blew from 1" valve. BH blew down to nothing in 2 min

By  Witness \_\_\_\_\_

(Position)