

State of New Mexico  
Energy, Minerals and Natural Resources Department

Susana Martinez  
Governor

David Martin  
Cabinet Secretary

Brett F. Woods, Ph.D.  
Deputy Cabinet Secretary

David R. Catanach, Division Director  
Oil Conservation Division



September 3, 2015

Mike Hanson  
Coleman Oil & Gas Inc  
PO Drawer 3337  
Farmington NM 87499

Re: Well Name: J W Goddard #3, UL\_K\_Sec\_11\_Twn\_26\_N-Rge\_12\_W,  
API # 30-045-05937

Dear Mr. Hanson:

The 2015 Bradenhead test on the above well indicates a failure. In order to comply with Rule 19.15.16.11, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before **90 days from letter date**. Initial Surface Casing psi of 138 was reported. Initial Production Casing psi of 72 was reported. The Surface Casing was opened for 30 minutes and the Production Casing did not drop.


Gas samples were taken by Coleman and the analysis were received in this office along with a wellbore schematic. The analysis shows that the bradenhead and production casing are the same, indicating communication.

Reference: RBDMS MPK1524629320 on future correspondence for this issue.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 123.

Sincerely yours,

  
Monica Kuehling  
Deputy Oil and Gas Inspector  
District III - Aztec

CC: Well File

