

State of New Mexico  
Energy, Minerals and Natural Resources Department

Susana Martinez  
Governor

David Martin  
Cabinet Secretary

Brett F. Woods, Ph.D.  
Deputy Cabinet Secretary

David R. Catanach, Division Director  
Oil Conservation Division



November 23, 2015

Mr. Travis Bandy  
BP America  
SJ OPER CTR  
200 S Energy Court  
Farmington NM 87401

**CERTIFIED MAIL**

**RETURN RECEIPT NO: 7013 1090 0001 7318 3961**

Re: Gallegos Canyon Unit #259, Unit Letter P, Sec.14, Twn. 28N, Rge. 12W,  
API # 30-045-20006

Dear Mr. Bandy:

On October 8, 2015, the above well failed a Mechanical Integrity test. In order to comply with Rule 19.15.16.11, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before **January 8<sup>th</sup>, 2016**.

A sundry detailing your proposed work is required to be submitted and approved before the work can begin. With your sundry please attach a current wellbore schematic including formation and cement tops. Indicate the method used to determine the cement tops.

Reference: RBDMS MPK1530953940 on future correspondence for this issue.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 116.

Sincerely yours,

Brandon Powell  
Deputy Oil and Gas Inspector  
District III - Aztec

CC: Well File