



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

AUG 10 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-10-15 Operator Kio Energy API #30-0 45-32985
Property Name Burger A Well No. 25 Location: Unit P Section 21 Township 26 Range 11
Well Status(Shut-In or Producing) Initial PSI: Tubing 13 Intermediate 44 Casing 38 Bradenhead 5046

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	43	38	0	33
10 min	0	43	37	0	32
15 min	0	43	36	0	30
20 min				0	28
25 min				0	28
30 min				0	28

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	<u>- Vapor</u>
Surges	
Down to Nothing	<u>✓</u>
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

BH - down to nothing in 3 seconds.
Diff when opened after 5 min shut in -
2nd - 4 sec blow to blue gas at 25 seconds to white

By Ryan Rybacki

Witness Monica Kuehling
at 32 seconds - to light blow at
55 seconds - Vapors - 10 min - 15
20 (light blow) lost shadow - 25 - 30
Gas analysis BH - blow when
opened after 5 min shut in

(Position)

E-mail address _____