

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

OCT 28 2015

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

## OPERATOR

☒ Initial Report ☒ Final Report

Name of Company WPX Energy Production	Contact Deborah Watson
Address PO Box 640 Aztec, NM 87410	Telephone No. 505-386-9693
Facility Name Rosa Unit 243	Facility Type Well Site
Surface Owner State	Mineral Owner State
API No. 30-039-24367	

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	36	32N	06W	1150	South	910	West	Rio Arriba

Latitude 36.93289 Longitude -107.41505

## NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 6 bbls	Volume Recovered 6 bbls
Source of Release Produced Water Tank	Date and Hour of Occurrence 10/23/15, 09:00	Date and Hour of Discovery 10/23/15, 09:00
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Transfer pump quit working as a result of pump cavitation, causing the produced water tank to overflow. Release consisted of 6 bbls of produced water. Water truck called to location to recover produced water. Transfer pump repaired.		
Describe Area Affected and Cleanup Action Taken.* <ul style="list-style-type: none"> <li>Produced water remained within secondary containment. No fluids migrated off location.</li> <li>Water truck recovered 6 bbls of produced water.</li> <li>Transfer pump repaired.</li> <li>No further action recommended.</li> </ul>		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Deborah Watson</i>	OIL CONSERVATION DIVISION	
Printed Name: Deborah Watson	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Environmental Specialist	Approval Date: 12/24/2015 Expiration Date:	
E-mail Address: deborah.watson@wpxenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/27/2015 Phone: 505-386-9693		

\* Attach Additional Sheets If Necessary

NUF 1535827539

①