Submit 1 Copy To Appropriate District Office	State of New Me			Form C-103
District I - (575) 393-6161	Energy, Minerals and Natu	iral Resources	WELL API NO.	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283			30-045-23524	
811 S. First St., Artesia, NM 88210	OIL CONSERVATION		5. Indicate Type of Lea	se
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fran		STATE 🛛	FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87	7505	6. State Oil & Gas Leas L-2986	e No.
87505 SLINDRY NOTI	ICES AND REPORTS ON WELLS	1	7. Lease Name or Unit	Agreement Name
(DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	SALS TO DRILL OR TO DEEPEN OR PL	UG BACK TO A	New Mexico State	Agreement Name
1. Type of Well: Oil Well	Gas Well Other OIL CONS	DIV DIST. 3	8. Well Number 1	
2. Name of Operator			9. OGRID Number	
Elm Ridge Exploration Co., LLC  3. Address of Operator	DEC	2 2 2015	149052 10. Pool name or Wildo	eat
PO Box 156, Bloomfield, NM 874	113		Nageezi Gallup	at
4. Well Location			0	
Unit Letter O :	790 feet from the SOUTH	line and 1'	750 feet from the	EAST line
Section 32	Township 24N	Range 8W	NMPM San Juan	County
	11. Elevation (Show whether DR)	, RKB, RT, GR, etc.		
	7019' KB			
10 (0) 1	Annual de Des de La Parte N	CNI-1'-	D Otl. D.	
12. Check A	Appropriate Box to Indicate N	ature of Notice,	Report or Other Data	
NOTICE OF IN	ITENTION TO:	SUB	SEQUENT REPOR	T OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR		RING CASING
TEMPORARILY ABANDON	CHANGE PLANS		ILLING OPNS.☐ P ANI	D A 🛛
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	T JOB	
DOWNHOLE COMMINGLE				
CLOSED-LOOP SYSTEM  OTHER:	П	OTHER:		П
	leted operations. (Clearly state all		d give pertinent dates, incl	uding estimated date
of starting any proposed wo	ork). SEE RULE 19.15.7.14 NMAG			
proposed completion or rec	ompletion.			
Elm Pidge Exploration CO	LLC has plugged and abandoned the	hic well as follows:	2.27.15: Move in Dig Un	
	40 sks of Class G Premium cement			
	'. Sting into retainer at 5218' and pu			
	' to 5353'. PLUG #3: Set balance p			
	from 4388' to 3570'. 2 <sup>nd</sup> stage: 65			
	cations out of the hole in the casing Pumped 15 sks of cement setting p			
	plug. <u>11-24-15</u> : <u>PLUG #6:</u> Shot 4			
	sks below retainer and left 15 sks o			
	35 sks of cement down hole. Fluid	, A A		A
	of cement at 145. Plug set from 250			
John Durham with the NMO	d outside of pipe. Pumped 13 bbls of CD witnessed all plugs	of slurry with ½ a b		
John Daniam Wild die 14440	ob winessed air piags.			ging of wellbore only.  It is retained pending
Spud Date: 5/16/1979	Rig Release Date:	12-2-15		ubsequent Report of We
nun				y be found @ OCD web
PNR on	9		page under forms www.emnrd.state.u	s/ocd
I hereby certify that the information	above is true and complete to the be	est of my knowledg	ge and benen.	3/000
SIGNATURE /	TITLE SE RO	oulstory Supervis	or DATE 12/12/2013	
SIGNATURE	THEE SI. Re	guiatory Supervis	OI DAIL_12/12/2013	
Type or print nameAmy Are	chuleta E-mail address: _aarcl	nuleta@elmridge.ne	et PHONE: 505-632-34	76 ext. 201
For State Use Only	1			
APPROVED BY. R.	DEPUTY	OIL & GAS	INSPECTOR DATE	12-28-15
APPROVED BY: Conditions of Approval (if any):	IIILE	DISTRICT #	3	0.00
Conditions of Approval (II ally).	R	<b>V</b>		29



iCem<sup>®</sup> Service

FINA KHIR-F FANITING IN MITTILL FRIE

For: MONTE STREIGAL

Date: Saturday, November 21, 2015

NEW MEXICO STATE 1 ELM RIDGE Job Date: Saturday, November 21, 2015

Sincerely,

**LEMONT JOJOLA** 

## Cementing Job Summary

The Road to Excellence Starts with Safety

Sold To #: 30205				365166			te #: 0022				der #: (	902	929382
Customer: ELM			7 5 5 5 10 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5			Cust	omer Rep	: MONT			150050	100	
Well Name: NEW	MEXICO				Vell #: 1				API/UWI				
ield:	The same	City (S	AP): BL	OOMF	IELD C	ounty/Pari	sh: SAN J	UAN	S	tate: N	EW ME	XIC	0
egal Descriptio	n:												
Contractor:					Rig/P	latform N	ame/Num	: Work C	over				
Job BOM: 7528													
Well Type: GAS										100	-		
Sales Person: H	ALAMERI	ICA\HX3	3057		Srvc		or: JACOB	AYERS			Charles Age		
		Section 1				Job	B. C. Cal	mar alea		2.333	(10) (E)		
Formation Name		_							77.0	200		_	
ormation Depth (	MDI	Тор				Bottom			-				
orm Type	MID)	ТОР				BHST							
lob depth MD		5300ft				Job Depth	TVD		-				
Vater Depth		COCOIL				Wk Ht Abo							
Perforation Depth	(MD)	From				То							
					N	Well Data							
Description	New /	Used	Size	ID	Weight	Th	read	Grade	e Top M	D Bot		ор	Botton
			in	in	lbm/ft				ft	100000		VD	TVD
`aaina			A.E.	4	116				0		00	ft	ft
Casing Tubing			4.5 2.375	1.995	11.6 4.6				0		00	-	
			1 (E) (24)			Fluid Data							
Stage/Plug #: 1	)		14.00						N SERVICE OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TO THE PERSON NAME				
Fluid # Stag	е Туре		Fluid I	Vama		Ohr	Qty UoM	Mixing	Yield	Mix	Rate	1 -	Total Mix
riui <del>u w</del> Stay	e Type		ridia	valle		Qty	Gty OOM		ft3/sack	Fluid	bbl/m		Fluid
								Ibm/gal		Gal	n		Gal
1 Plu	gCem	PLUG	СЕМ (Т	M) SYS	STEM	300	sack	15.8	1.16		2		5.08
0.20 %	900	. 200	(.	,			50 LB SK						Name of the last
0.20 70						11110,	OU ED OIL	(100000					
Cement Left In	Pipe A	mount					Reason				Shoe Jo	int	9834
	-		Name of Street	-	-	Fluid Data		Name of Street		-	-	-	-
Stage/Plug #: 2	-			20,00		riulu Data		Allert And Allert			-		Part Tri
ragen lag m. L													
Fluid # Stag	е Туре		Fluid N	Vame		Qty	Qty UoM	Mixing	Yield	Mix	Rate	1	Total Mix
		CONTRACTOR OF THE PARTY OF THE							ft3/sack	Fluid	bbl/mi	1000	Fluid
								lbm/gal		Gal	n		Gal
1 Plu	gCem	PLUG	CEM (T	M) SYS	TEM	373	sack	15.8	1.16	PIE	2		5.08
Cement Left In	Dine A	mount				Die	Reason				Shoe Jo	int	
Cement Len In	ipe A	mount					Reason				Olive Jo	HIL	

Customer: ELM RIDGE EXPLORATION CO LLC - EBUS

Job: PLUG TO ABANDON

Case: ELM RIDGE | SO#: 092929382

#### 1.0 Real-Time Job Summary

ob Eve	nt Log				31-13					4	
Туре	Seq. No.	Activity	Graph Label	Date	Time	Source	Pass-Side Pump Pressure (psi)	Downhole Density (ppg)	Pass-Side Pump Rate (bbl/min)	PS Pmp Stg Tot (bbl)	Comments
Event	1	Call Out	Call Out	11/21/201 5	02:00:00	USER			4		CEMENT CREW CALLED
Event	2	Depart Yard Safety Meeting	Depart Yard Safety Meeting	11/21/201 5	04:10:00	USER					SAFETY MEETING HELD WITH CEMENT CREW
Event	3	Depart Home for Location	Depart Home for Location	11/21/201 5	04:30:00	USER	E		=1		1- PICKUP 11583927, 1- RED TIGER 12638114, 2- BULK TRUCKS 10897849/ 10025041, 11338219/10001398, 1- BODYLOAD 10793626
Event	4	Arrive At Loc	Arrive At Loc	11/21/201 5	06:00:00	USER					CEMENT CREW ARRIVED TO LOCATION
Event	5	Other	Other	11/21/201 5	06:10:00	USER			С	,	RETAINER SET @ 5218 FT 2 3/8 TUBING 4 1/2 10.5# CASING
Event	6	Pre-Rig Up Safety Meeting	Pre-Rig Up Safety Meeting	11/21/201 5	06:20:00	USER					SAFETY MEETING HELD WITH CEMENT CREW
Event	7	Rig-Up Equipment	Rig-Up Equipment	11/21/201 5	06:30:00	USER					CEMENT CREW RIGGED UP EQUIPMENT
Event	8	Pre-Job Safety Meeting	Pre-Job Safety Meeting	11/21/201 5	09:00:00	USER	314.00	8.54	5.00	15.0	SAFETY MEETING HELD WITH EVERYONE ON LOCATION
Event	9	Start Job	Start Job	11/21/201 5	09:15:15	COM5	-1.00	8.24	0.00	0.0	
Event	10	Start Job	Start Job	11/21/201 5	09:31:46	COM5	-3.00	8.22	0.00	0.0	
Event	11	Pressure Test	Pressure Test	11/21/201	09:33:20	USER	1679.00	8.30	0.00	0.2	PRESSURE TEST GOOD TO

iCem® Service

(v. 4.1.107)

Created: Saturday, November 21, 2015

Customer: ELM RIDGE EXPLORATION CO LLC - EBUS

Job: PLUG TO ABANDON

Case: ELM RIDGE | SO#: 092929382

	16			5							2500 PSI
Event	12	Pump Spacer	Pump Spacer	11/21/201 5	09:36:17	USER	-8.00	7.91	1.20	0.3	PUMPED 8 BBLS H2O
Event	13	Pump Cement	Pump Cement	11/21/201 5	09:41:52	USER	946.00	10.35	1.50	0.2	20 KS 1.16 CUFT/SK 5.08  GAL/SK = 4.1 BBLS @  15.8# 2.4 BBLS H2O REQ: PER COMANY REP HES WILL PUMP 10 SKS OFCEMENT BELOW THE RETAINER AND 10 SKS ABOVE THE RETAINER
Event	14	Pump Displacement	Pump Displacement	1 <b>1/21/20</b> 1 5	09:44:44	USER	508.00	16.86	1.60	0.3	CALCULATED 18.2 BBLS TO DISPLACE CEMENT
Event	15	Shutdown	Shutdown	1 <b>1/</b> 21/ <b>2</b> 01 5	09:54:16	USER	349.00	8.30	0.00	18.7	SHUTDOWN RIG CREW WILL POOH

Customer: ELM RIDGE EXPLORATION CO LLC - EBUS

Job: PLUG TO ABANDON

Case: EML RIDGE | SO#: 902929382

### 1.0 Real-Time Job Summary

1.1	Job	Event	Log
-----	-----	-------	-----

	A made stars	Canala Lakal	Date	40-7	C	D 01-1-	man to all	D CI I.	DC D	
Seq. No.	Activity	Graph Label	Date	Time	Source	Pass-Side Pump Pressure (psl)	Downhole Density (ppg)	Pass-Side Pump Rate (bbl/min)	PS Pmp Stg Tot (bbl)	Comments
1	Other	Other	11/21/201 5	11:45:56	USER	-9.00	8.27	0.00	65.0	TUBING SET @ 4388 FT 818 FT PLUG
2	Pressure Test	Pressure Test	11/21/201 5	11:57:12	USER	1771.00	8.24	0.00	0.1	PRESSURE TEST GOOD TO 2500 PSI
3	Pump Cement	Pump Cement	11/21/201 5	12:08:56	USER	496.00	16.45	2.50	2.0	63 SKS 1.16 CUFT/SK 5.08 GAL/SK = 13 BBLS 15.8# 7.6 BBLS H2O REQ
4	Pump Displacement	Pump Displacement	11/21/201 5	12:14:09	USER	22.00	8.68	2.50	1.4	CALCULATED 13.4 BBLS TO DISPLACE AND BALANCE PLUG
5	Shutdown	Shutdown	11/21/201 5	12:19:42	USER	0.00	7.80	0.00	14.2	SHUTDOWN RIG CREW TO POOH TO 3570FT
6	Reverse Circ Well	Reverse Circ Well	11/21/201 5	12:41:05	USER	-11.00	7.72	0.00	14.2	RIG CREW PUMPED 20 BBLS H2O, TUBING CLEAN .5 BBLS OF CEMENT BACK
7	Other	Other	11/21/201 5	13:01:49	USER	-12.00	7.73	0.00	14.2	TUBING SET@ 3570 FT 796 FT PLUG
8	Pump Cement	Pump Cement	11/21/201 5	13:08:15	USER	307.00	15.95	2.30	2.0	61 SKS 1.16 CUFT/SK 5.08 GAL/SK = 12.6 BBLS 15.8# 7.4 BBLS H2O REQ
9	Pump Displacement	Pump Displacement	11/21/201 5	13:14:12	USER	10.00	8.04	2.30	1.3	CALCULATED 10.4 BBLS TO DISPLACE AND BALANCE PLUG
10	Shutdown	Shutdown	11/21/201 5	13:18:24	USER	30.00	0.40	0.00	10.7	SHUTDOWN RIG CREW TO POOH TO 2774 FT
11	Reverse Circ Well	Reverse Circ Well	11/21/201 5	13:40:13	USER	-11.00	-0.77	0.00	10.7	RIG CREW PUMPED 15 BBLS H2O, TUBING CLEAN .5
	1 2 3 4 5 6 7 8 9 10	1 Other 2 Pressure Test 3 Pump Cement 4 Pump Displacement 5 Shutdown 6 Reverse Circ Well 7 Other 8 Pump Cement 9 Pump Displacement 10 Shutdown	1 Other Other 2 Pressure Test Pressure Test 3 Pump Cement Pump Cement 4 Pump Displacement Pump Displacement 5 Shutdown Shutdown 6 Reverse Circ Well Reverse Circ Well 7 Other Other 8 Pump Cement Pump Displacement 9 Pump Displacement Pump Displacement 10 Shutdown Shutdown	No.         1         Other         11/21/201           2         Pressure Test         Pressure Test         11/21/201           3         Pump Cement         Pump Cement         11/21/201           4         Pump Displacement         Pump Displacement         11/21/201           5         Shutdown         Shutdown         11/21/201           6         Reverse Circ Well         Reverse Circ Well         11/21/201           7         Other         Other         11/21/201           8         Pump Cement         Pump Cement         11/21/201           9         Pump Displacement         Pump Displacement         11/21/201           10         Shutdown         Shutdown         11/21/201           11         Reverse Circ Well         Reverse Circ Well         11/21/201	No.         1 Other       Other       \$\frac{11}{21}\frac{1}{201}\$ 11:45:56         2 Pressure Test       \$\frac{11}{21}\frac{1}{201}\$ 11:57:12         3 Pump Cement       Pump Cement       \$\frac{11}{21}\frac{1}{201}\$ 12:08:56         4 Pump Displacement       Pump Displacement       \$\frac{11}{21}\frac{1}{201}\$ 12:14:09         5 Shutdown       Shutdown       \$\frac{11}{21}\frac{1}{201}\$ 12:19:42         6 Reverse Circ Well       Reverse Circ Well       \$\frac{11}{21}\frac{1}{201}\$ 12:41:05         7 Other       Other       \$\frac{11}{21}\frac{1}{201}\$ 13:01:49         8 Pump Cement       Pump Displacement       \$\frac{11}{21}\frac{1}{201}\$ 13:08:15         9 Pump Displacement       Pump Displacement       \$\frac{11}{21}\frac{1}{201}\$ 13:14:12         10 Shutdown       Shutdown       \$\frac{11}{21}\frac{1}{201}\$ 13:18:24         11 Reverse Circ Well       Reverse Circ Well       \$\frac{11}{21}\frac{1}{201}\$ 13:16:13	No.       1       Other       11/21/201 5       11:45:56 USER         2       Pressure Test       11/21/201 5       11:57:12 USER         3       Pump Cement       11/21/201 5       12:08:56 USER         4       Pump Displacement       Pump Displacement       11/21/201 12:14:09 USER         5       Shutdown       11/21/201 5       12:19:42 USER         6       Reverse Circ Well       Reverse Circ Well 5       11/21/201 12:41:05 USER         7       Other       Other       11/21/201 5       13:01:49 USER         8       Pump Cement       Pump Cement 11/21/201 5       13:08:15 USER         9       Pump Displacement       Pump Displacement 11/21/201 5       13:14:12 USER         10       Shutdown       Shutdown Shutdown 5       11/21/201 13:18:24 USER         11       Reverse Circ Well 5       Pewerse Circ Well 12:40:13 USER	Pump Pressure   Pump Pressure   Pump Pressure   Pump Pressure   Pump Pressure   Pump Pressure   Pressure   Pressure   Pressure   Pressure   Pressure   Pressure   Pressure   Pump Pressure	No.    Pump Pressure   Pump Pressure   Pump   Pressure   Pump   Pressure   Pump   Pressure   Pump   Pressure   Pump   Pressure   Pump   Pressure   Pump   Pressure   Pump   Pump   Pressure   Pump   Pump   Pump   Pump   Pressure   Pump   Pump	No.   Pump   Pressure   Pump   Pressure   Pump   Pressure   Pump   Pressure   Pressure	No.   Pensure   Pressure   Pres

iCem® Service

(v. 4.1.107) Created: Saturday, November 21, 2015

Customer: ELM RIDGE EXPLORATION CO LLC - EBUS

Job: PLUG TO ABANDON

Case: ELM RIDGE | SO#: 902929382

#### 1.0 Real-Time Job Summary

Job Eve	nt Log			V. 11 (4)			100				
Туре	Seq. No.	Activity	Graph Label	Date	Time	Source	Pass-Side Pump Pressure (psi)	Downhole Density (ppg)	Pass-Side Pump Rate (bbl/min)	PS Pmp Stg Tot (bbl)	Comments
Event	1	Start Job	Start Job	11/22/201 5	10:58:50	COM5	76.00	8.49	0.00	0.0	
Event	2	Other	Other	11/22/201 5	11:21:08	USER	32.00	8.43	0.00	0.0	TUBING SET @ 1906 FT HOLES @ 460 FT
Event	3	Circulate Well	Circulate Well	11/22/201 5	11:22:56	USER	108.00	8.43	1.80	0.9	PER COMPANY MAN CIRCULATE DOWN TUBING UNTIL ALL THE PRODUCED WATER IS OUT PUMPED 40 BBLS
Event	4	Circulate Well	Circulate Well	11/22/201 5	11:38:41	USER	14.00	8.32	0.00	37.0	RIG CREW CLOSED CASING VALVE CIRCULATE TILL CLEAN
Event	5	Shutdown	Shutdown	11/22/201 5	12:20:27	USER	61.00	8.40	0.00	57.1	SHUTDOWN PUMPED 58 BBLS
Event	6	End Job	End Job	11/22/201 5	12:24:56	COM5	-1.00	8.42	0.00	0.0	

Customer: ELM RIDGE EXPLORATION CO LLC - EBUS

Job: NEW MEXICO # PLUG 5

Case: NEW MEXICO #1 PLUG 6 | SO#: 902929382

#### 1.0 Real-Time Job Summary

#### 1.1 Job Event Log

Туре	Seq. No.	Activity	Graph Label	Date	Time	Source	PS Pump Press (psi)	DH Density (ppg)	PS Pump Rate (bbl/min)	PS Pmp Stg Tot (bbl)	Comments
Event	1	Start Job	Start Job	11/23/201 5	14:52:35	сом10	-8.00	8.51	0.00	2.1	
Event	2	Circulate Well	CIRCULATE WELL	11/23/201 5	15:08:40	USER	0.00	8.37	1.30	0.1	ESTABLISH RETURNS 1.5BBL
Event	3	Pump Cement	Pump Cement	11/23/201 5	15:14:49	USER	64.00	17.82	1.40	1.2	PUMP 2.9 BBL 14SKS @ 15.8# YIELD 1,16 WR 5,08 WRQ 2.7BBL
Event	4	Pump Displacement	Pump Displacement	11/23/201 5	15:17:06	USER	7.00	8.55	2.00	1.7	CALCULATED DISPLACEMENT TO BALANCE 4.55BBL
Event	5	Other	PULL UP	11/23/201 5	15:20:25	USER	-3.00	0.00	0.00	4.3	250' OF TUBING
Event	6	Circulate Well	Circulate Well	11/23/201 5	15:22:22	USER	-3,00	0.00	0.00	4.3	RIG CIRCULATED HOLE .5BBL DIRTY WATER BACK
Event	7	End Job	End Job	11/23/201 5	15:25:00	USER	-4.00	0.00	0.00	4.3	

Customer: ELM RIDGE EXPLORATION CO LLC - EBUS

Job: PTA PLUG 7

Case: PTA PLUG #7 | SO#: 902929382

#### 1.0 Real-Time Job Summary

INJECTION RATE

Pressure Test

End Job

5

5

11/24/201

11/24/201

5

#### 1.1 Job Event Log Type Seq. Activity Graph Label Date Time PS Pump DH PS Pump PS Pmp Stg Source Comments No. Press Density Tot Rate (psi) (ppg) (bbl/min) (bbl) 11/24/201 08:54:37 USER Event 1 Call Out Call Out 215.00 8.35 0.00 18.2 CALL OUT @ 330 5 Depart from Service 11/24/201 Depart from Service 08:56:42 USER 215.00 0.00 18.2 Event 2 8.36 LEFT THE YARD @ 545 5 Center or Other Site Center or Other Site Arrive at Location from 11/24/201 ARRIVED ON LOCATION @ Arrive at Location from 08:57:08 USER 216.00 8.35 0.00 18.2 Event 5 Service Center Service Center 11/24/201 Event Start Job Start Job 09:05:17 COM10 217.00 7.90 0.00 0.0 5 GOT INJECTION RATE @ .7 CIRCULATE AND GET 11/24/201 09:09:00 USER 220.00 8.38 0.00 0.0 5 Circulate Well BPM SPOT CMT 1 BBL Event

39 SKS @ 15.8 # 8 BBL 4.7 11/24/201 BBL WRQ PUMPED 3 BBL 09:20:02 USER **Pump Cement Pump Cement** 538.00 8.37 1.10 0.6 Event 5 CMT STING IN PUMP **REMAINING 5 BBL** 11/24/201 PUMP 1.2 STING OUT **Pump Displacement** Pump Displacement 09:39:00 USER 1108.00 13.38 1.10 0.4 Event **PUMPED 1.5 TO BALLANCE RIG PULLED 7 STICKS AND** 11/24/201 9 Other Other 09:41:47 USER -2.008.54 0.00 2.6 CIRCULATED OFF THE TOP Event 5 .25 BBL BACK TO SURFACE

3178.00

-1.00

8.44

8.29

0.00

0.00

09:16:15 USER

10:09:39 COM10

FROM RETAINER

PSI TEST TO 3300

0.9

33.5

Event

10

Event

End Job

**Pressure Test** 

Customer: ELM RIDGE EXPLORATION CO LLC - EBUS

Job: PLUG TO ABANDON

Case: EML RIDGE | SO#: 902929382

#### BBLS OF CEMENT BACK

Event	12	Other	Other	11/21/201 5	13:57:54	USER	-12.00	-0.77	0.00	10.7	TUBING SET @ 2774 FT 868 FT PLUG
Event	13	Pump Cement	Pump Cement	11/21/201 5	14:01:27	USER	311.00	16.21	2.50	2.6	66.8 SKS 1.16 CUFT/SK 5.08 GAL/SK = 13.8 BBLS 15.8# 8 BBLS H2O REQ
Event	14	Pump Displacement	Pump Displacement	11/21/201 5	14:08:05	USER	14.00	7.98	2.60	1.5	CALCULATED 7 BBLS TO DISPLACE AND BALANCE PLUG
Event	15	Shutdown	Shutdown	11/21/201 5	14:10:08	USER	-6.00	-0.77	0.00	5.5	SHUTDOWN
Event	16	Reverse Circ Well	Reverse Circ Well	11/21/201 5	14:18:13	USER	-13.00	-0.77	0.00	5.5	PUMPED 175BBLS H2O, TUBING CLEAN 1 BBLS OF CEMENT BACK
Event	17	End Job	End Job	11/21/201 5	14:45:31	COM5	-11.00	7.70	0.00	0.0	

Customer: ELM RIDGE EXPLORATION CO LLC - EBUS

Job: PTA PLUG 8

Case: NEW MEXICO #1 | SO#: 902929382

#### 1.0 Real-Time Job Summary

#### 1.1 Job Event Log

Туре	Seq. No.	Activity	Graph Label	Date	Time	Source	PS Pump Press (psi)	DH Density (ppg)	PS Pump Rate (bbl/min)	PS Pmp Stg Tot (bbl)	Comments
Event	1	Pressure Test	Pressure Test	11/25/201 5	07:46:22	USER	3134.00	8.71	0.00	1.3	PSI TEST TO 3300
Event	2	Pump Spacer	Pump Spacer	11/25/201 5	07:49:21	USER	121.00	8.61	1.00	0.0	ATTEMPTED TO ESTABLISH CIRCULATION THROUGH RETAINER BUT COULD NOT PUMP THROUGH IT
Event	3	Call Out	Call Out	11/25/201 5	12:25:23	USER	11 11 11 14 1	Ja Sau			called out @ 430
Event	4	Depart from Service Center or Other Site	Depart from Service Center or Other Site	11/25/201 5	12:25:37	USER		- T			LEFT YARD @ 545
Event	5	Arrive at Location from Service Center	Arrive at Location from Service Center	11/25/201 5	12:26:30	USER					ARRIVED ON LOCATION @

Customer: ELM RIDGE EXPLORATION CO LLC - EBUS

Job: PTA DAY 6

Case: ELM RIDGE | SO#: 902929382

#### 1.0 Real-Time Job Summary

Job Eve	nt Log										
Туре	Seq. No.	Activity	Graph Label	Date	Time	Source	Pass-Side Pump Pressure (psi)	Downhole Density (ppg)	Pass-Side Pump Rate (bbl/min)	PS Pmp Stg Tot (bbl)	Comments
Event	1	Call Out	Call Out	11/30/201 5	04:30:00	USER					CEMENT CREW CALLED OUT
Event	2	Depart Yard Safety Meeting	Depart Yard Safety Meeting	11/30/201 5	06:00:00	USER					SAFETY MEETING HELD WITH CEMENT CREW
Event	3	Depart Home for Location	Depart Home for Location	11/30/201 5	06:10:00	USER					CEMENT CREW DEPARTS YARD
Event	4	Arrive At Loc	Arrive At Loc	11/30/201 5	07:00:00	USER					CEMENT CREW ARRIVESON LOCATION
Event	5	Pre-Rig Up Safety Meeting	Pre-Rig Up Safety Meeting	11/30/201 5	07:20:00	USER		1-11			SAFETY MEETING HELD WITH CEMENT CREW
Event	6	Rig-Up Equipment	Rig-Up Equipment	11/30/201 5	07:30:00	USER					CEMENT CREW RIGGS UP EQUIPMENT
Event	7	Other	Other	11/30/201 5	08:00:00	USER	63.00	8.19	0.00	14.9	RETAINER SET @ 300 FT 2 3/8 TUBING, 4 1/2 10.5# CASING, HOLES ARE @ 350 FT
Event	8	Pre-Job Safety Meeting	Pre-Job Safety Meeting	11/30/201 5	08:10:49	USER	18.00	8.18	0.00	14.9	SAFETY MEETING HELD WITH EVERYONE ON LOCATION
Event	9	Pressure Test	Pressure Test	11/30/201 5	08:30:15	USER	2193.00	8.04	0.00	15.0	PRESSURE TEST GOOD TO 1575 PSI
Event	10	Start Job	Start Job	11/30/201 5	08:30:46	COM5	1650.00	8.07	0.00	15.0	
Event	11	Pump Spacer	Pump Spacer	11/30/201 5	09:17:28	USER	17.00	6.99	1.00	0.3	PUMPED 1.5 BBLS H2O
Event	12	Shutdown	Shutdown	11/30/201	09:18:57	USER	403.00	8.23	0.00	1.3	SHUTDOWN MIX UP

iCem® Service

(v. 4.1.107)

Created: Monday, November 30, 2015

Customer: ELM RIDGE EXPLORATION CO LLC - EBUS

Job: PTA DAY 6

Case: ELM RIDGE | SO#: 902929382

				5							CEMENT
Event	13	Pump Cement	Pump Cement	11/30/201 5	09:23:29	USER	517.00	11.26	0.70	0.5	36.5 SKS 1.16 CUFT/SK 5.08 GAL/SK = 7.5 BBLS @ 15.8# 4.4 BBLS H2O REQ
Event	14	Pump Displacement	Pump Displacement	11/30/201 5	09:36:56	USER	34.00	13.17	1.00	0.3	CALCULATED .6 BBLS TO BALANCE 2 BBLS ON TOP OF THE RETAINER
Event	15	Shutdown	Shutdown	11/30/201 5	09:37:29	USER	-1.00	11.96	0.00	0.5	SHUTDOWN

Customer: ELM RIDGE EXPLORATION CO LLC - EBUS

Job: pta day 8


Case: PTA DAY N8 | SO#: 902929382

#### 2.0 Real-Time Job Summary

Job Event Log											
Туре	Seq. No.	Activity	Graph Label	Date	Time	Source	PS Pump Press (psi)	DH Density (ppg)	PS Pump Rate (bbl/min)	PS Pmp Stg Tot (bbl)	Comments
Event	1	Other	Other	12/1/2015	09:00:00	USER					ARRIVED ON LOCATION ON 12/1/15 @ 0900 WAS RELEASED @ 1300 DIDN'T PUIMP ANY THING
Event	2	Call Out	Call Out	12/2/2015	04:00:00	USER					CALLED OUT @ 400
Event	3	Pre-Convoy Safety Meeting	Pre-Convoy Safety Meeting	12/2/2015	04:30:00	USER				11	PRE CONVOY MEETING @ 630 ONE F-450 11583926
Event	4	Arrive at Location from Service Center	Arrive at Location from Service Center	12/2/2015	07:45:00	USER		11.			ARRIVED ON LOCATION @ 745
Event	5	Pre-Rig Down Safety Meeting	Pre-Rig Down Safety Meeting	12/2/2015	08:00:00	USER				ů .	WITH CREW
Event	6	Start Job	Start Job	12/2/2015	08:33:00	COM10	111.00	8.28	0.00	0.2	START JOB @ 833
Event	7	Pressure Test	Pressure Test	12/2/2015	08:34:11	USER	2864.00	8.21	0.00	0.3	PRESSURE TEST TO 2500
Event	8	Pump Spacer	Pump Spacer	12/2/2015	08:36:36	USER	-12.00	8.23	0.80	0.0	PUMPED 1 BBL TO ESTABLISH CIRCULATION
Event	9	Pump Cement	Pump Cement	12/2/2015	08:43:06	USER	3.00	11.03	1.60	0.4	65 SKS CMT G NEAT @ 15.8# 13 BBL
Event	10	Cement Returns to Surface	Cement Returns to Surface	12/2/2015	09:02:54	USER	-18.00	15.87	1.60	11.1	CMT RETURNS TO SURFACE 3 BBL GOOD CMT
Event	11	End Job	End Job	12/2/2015	09:07:50	COM10	-30.00	15.85	0.00	0.0	END JOB @ 907

WATER TEST SULFATES <200 CLORIDES >100 TEMP 34 TDS 110 IRON 0 PH 6.5

## ELM RIDGE NEW MEXICO STATE #1, PTA



PS Pump Press (psi) -4 DH Density (ppg) 8.32 PS Pump Rate (bbl/min) 0 PS Pmp Stg Tot (bbl) 36.5

1 Call Out

Arrive At Loc

Tig-Up Equipment

1 Start Job

**13** Pump Cement

2 Depart Yard Safety Meeting

(5) Other

® Pre-Job Safety Meeting

1 Pressure Test

Pump Displacement

3 Depart Home for Location

6 Pre-Rig Up Safety Meeting 9 Start Job

@ Pump Spacer

15 Shutdown

HALLIBURTON | iCem® Service

Created: 2015-11-20 15:21:50, Version: 4.1.107

Edit

- Customer: ELM RIDGE EXPLORATION CO LLC -

**EBUS** 

Représentative: LEMONT JOJOLA / AR 8114


Job Date: 11/21/2015 7:47:35 AM

Sales Order #: 092929382

Well: NEW MEXICO STATE #1

COMPANY MAN: MONTE STREIGAL

## ELM RIDGE NEW MEXICO STATE 1, PTA PLUGS 2,3,4



PS Pump Press (psi) DH Density (ppg) PS Pump Rate (bbl/min) PS Pmp Stg Tot (bbl)

1 Other

Shutdown

Pump Displacement Pump Cement

1 End Job

2 Pressure Test

6 Reverse Circ Well

10 Shutdown

Pump Displacement

3 Pump Cement

7 Other

(1) Reverse Circ Well

1 Shutdown

**® Pump Cement** Pump Displacement

12 Other

16 Reverse Circ Well

▼ HALLIBURTON | iCem® Service

Created: 2015-11-21 10:20:55, Version: 4.1.107

Edit

- Customer: ELM RIDGE EXPLORATION CO LLC -

**EBUS** 

Représentative: LEMONT JOJOLA / AR 8114


Job Date: 11/21/2015 10:43:31 AM

Sales Order #: 902929382

Well: NM STATE 1 PLUGS 2,3,4

**COMPANY MAN: MONTE STREIGAL** 

## ELM RIDGE NEW MEXICO STATE 1, PTA CLEANOUT



① Start Job ④ Circulate Well

② Other ⑤ Shutdown

3 Circulate Well 6 End Job

▼ HALLIBURTON | iCem® Service

Created: 2015-11-22 10:47:51, Version: 4.1.107

Edit

COMPANY MAN: MONTE STREIGAL

Well: NEW MEXICO STATE #1

- Customer: ELM RIDGE EXPLORATION CO LLC -


EBUS

Représentative: LEMONT JOJOLA / AR 8114

Job Date: 11/22/2015 10:50:11 AM

Sales Order #: 902929382

#### Custom Results



PS Pump Press (psi) -7 DH Density (ppg) 8.44 PS Pump Rate (bbl/min) 0 PS Pmp Stg Tot (bbl) 0

① Call Out

- 4 Depart from Service Center or Other Site 7 Pre-Job Safety Meeting

- 10 Pump Spacer
- **3 STING OUT**

1 End Job


- 2 PRE CONVOY SAFETY MEETING
- (5) Arrive at Location from Service Center
- ® Start Job

- 1 Pump Cement
- (4) Circulate Well

3 Other


- 6 Pre-Rig Up Safety Meeting
- Pressure Test
- 12 Shutdown
- 15 Cement Returns to Surface


#### NEW MEXICO #1 PLUG 6



PS Pump Press (psi) 1 DH Density (ppg) 0 PS Pump Rate (bbl/min) 0 PS Pmp Stg Tot (bbl) 75.4

#### Custom Results






4 Start Job 217;7.9;0;0 Pump Cement 538;8.37;1.1;0.6 @ End Job -1;8.29;0;33.5

- ② Depart from Service Center or Other Site 215;8.36;0;18.2 ⑤ CIRCULATE AND GET INJECTION RATE 220;8.38;0;0
- ® Pump Displacement 1108;13.38;1.1;0.4

3 Arrive at Location from Service Center 216;8.35;0;18.2 6 Pressure Test 3178;8.44;0;0.9 9 Other-2;8.54;0;2.6

#### **ELM RIDGE NEW MEXICO #1 PTA #8**



- ① Pressure Test 3134;8.71;0;1.3 ④ Depart from Service Center or Other Site n/a;n/a;n/a;n/a
- 2 Pump Spacer 121;8.61;1;0
- (5) Arrive at Location from Service Center n/a;n/a;n/a;n/a
- 3 Call Out n/a;n/a;n/a;n/a

#### ▼ HALLIBURTON | iCem® Service

Created: 2015-11-25 07:31:37, Version: 4.1.107

Edit

Customer: ELM RIDGE EXPLORATION CO LLC-

**EBUS** 

Representative: JACOB AYERS- JE 8114


Job Date: 11/25/2015 7:33:31 AM

Sales Order #: 902929382

Well: NEW MEXICO #1

**CUSTOMER REP: MONTE STREIGAL** 

## ELM RIDGE NEW MEXICO STATE 1, PTA DAY 6



PS Pump Press (psi) DH Density (ppg) PS Pump Rate (bbl/min) PS Pmp Stg Tot (bbl)

① Call Out

Arrive At Loc

7 Other

Start Job

13 Pump Cement

② Depart Yard Safety Meeting

⑤ Pre-Rig Up Safety Meeting

® Pre-Job Safety Meeting

Pump Spacer

**19** Pump Displacement

3 Depart Home for Location

**6** Rig-Up Equipment

Pressure Test

1 Shutdown

19 Shutdown

▼ HALLIBURTON | iCem® Service

Created: 2015-11-30 05:18:32, Version: 4.1.107

Edit

. Customer: ELM RIDGE EXPLORATION CO LLC -

EBUS

Représentative : LEMONT JOJOLA


Job Date: 11/30/2015 7:36:25 AM

Sales Order #: 902929382

Well: NEW MEXICO STATE 1

COMPANY MAN: MONTY STREIGAL

#### NEW MEXICO #1 PTA DAY 8



▼ HALLIBURTON | iCem® Service

Well: NEW MEXICO #1

Created: 2015-12-02 08:23:54, Version: 4.1.107

Edit

**COMPANY MAN: MONTY STRIEGLE** 

Customer: ELM RIDGE EXPLORATION CO LLC -EBUS

₹ Représentative : JACOB AYERS JE -0112

Sales Order #: 902929382

Job Date: 12/2/2015 8:26:17 AM