

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

OIL CONS. DIV DIST. 3

DEC 30 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ConocoPhillips Company	Contact Lisa Hunter	
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9525	
Facility Name: San Juan 28-7 Unit 153E	Facility Type: Gas Well	
Surface Owner Federal	Mineral Owner Federal (SF-078640)	API No. 3003925883

LOCATION OF RELEASE



Unit Letter I	Section 20	Township 27N	Range 07W	Feet from the 1460	North/South Line South	Feet from the 795	East/West Line East	County Rio Arriba
-------------------------	----------------------	------------------------	---------------------	------------------------------	----------------------------------	-----------------------------	-------------------------------	-----------------------------

Latitude **36.55508** Longitude **-107.59182**

NATURE OF RELEASE

Type of Release Condensate & Produced Water	Volume of Release 82bbl & 7bbls	Volume Recovered 7bbls
Source of Release Production Tank	Date and Hour of Occurrence 12/18/15 @ 7:00 a.m.	Date and Hour of Discovery 12/22/15 @ 11:15 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Vanessa Fields, OCD Katherina Diemer, BLM	
By Whom? Lisa Hunter	Date and Hour 12/22/15 1:37 p.m. (OCD); 1:44 p.m. (BLM)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Manway leaked due on Production Tank. Leak was discovered during routine tank gauging. Truck was called to remove standing fluids. Tank will be repaired.		
Describe Area Affected and Cleanup Action Taken.* ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary. Location is ranked 0.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Lisa Hunter		
Title: Field Environmental Specialist	Approval Date: 12/31/2015	Expiration Date:
E-mail Address: Lisa.Hunter@cop.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: December 28, 2015 Phone: (505) 258-1607		

* Attach Additional Sheets If Necessary

Remediation Must occur by January 30, 2015
NVF 1535834306