

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

OIL CONS. DIV DIST. 3

JAN 07 2016

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☒ Final Report

Name of Company WPX Energy Production	Contact Deborah Watson
Address PO Box 640	Telephone No. 505-386-9693
Facility Name Chaco 2408 32P #114H	Facility Type Well Site

Surface Owner State	Mineral Owner State	API No. 30-045-35441
---------------------	---------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	32	24N	08W	1203	South	382	East	San Juan

Latitude N36.266987 Longitude W107.697511

**NATURE OF RELEASE**

Type of Release Flash Fire /oil and water	Volume of Release 0.75 bbl	Volume Recovered 0.0 bbl
Source of Release Hot oil truck (contractor)	Date and Hour of Occurrence 12/31/15 8:30 AM	Date and Hour of Discovery 12/31/15 8:30 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Vanessa Fields (NMOCD)	
By Whom? N/A	Date and Hour 12/31/15 10:39AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*  
N/A



Describe Cause of Problem and Remedial Action Taken.\*

While trying to unfreeze pump, 2-inch rubber hose broke loose and sprayed fluid onto coils resulting in a flash fire. Driver acquired fire extinguisher and promptly extinguished fire.

Describe Area Affected and Cleanup Action Taken.\*

- No injuries. Fire extinguished by driver within minutes. No equipment damage on location/ fire extinguished before truck was impacted.
- Impacted soils were cleaned up and removed for disposal.
- No fluids migrated off location.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Deborah Watson	Approved by Environmental Specialist: 	
Title: Environmental Specialist	Approval Date: 1/8/2016	Expiration Date:
E-mail Address: deborah.watson@wpxenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 01/05/2016 Phone: 505-386-9693/505-333-1880		

\* Attach Additional Sheets If Necessary

NUF1536540194