

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

OIL CONS. DIV DIST. 3

FEB 03 2016

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Burlington Resources Oil & Gas Co.	Contact Bobby Spearman
Address 3401 East 30 <sup>th</sup> St, Farmington, NM	Telephone No. (505)-320-3045
Facility Name: Decker 3	Facility Type: Gas well

Surface Owner: Fee	Mineral Owner: Fee	API No. 3004560068
--------------------	--------------------	--------------------

LOCATION OF RELEASE

Unit Letter <b>M</b>	Section <b>23</b>	Township <b>32</b>	Range <b>12</b>	Feet from the <b>1090</b>	North/South Line <b>South</b>	Feet from the <b>890</b>	East/West Line <b>West</b>	County <b>San Juan</b>
-------------------------	----------------------	-----------------------	--------------------	------------------------------	----------------------------------	-----------------------------	-------------------------------	---------------------------

Latitude \_ Longitude  
NATURE OF RELEASE

Type of Release Condensate	Volume of Release 22.3 bbl	Volume Recovered 0 bbl
Source of Release Production tank	Date and Hour of Occurrence <b>1-27-16 11:15A</b>	Date and Hour of Discovery <b>same</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



OIL CONS. DIV DIST. 3

FEB 03 2016

Describe Cause of Problem and Remedial Action Taken.\*  
Hole in tank due to corrosion.

Describe Area Affected and Cleanup Action Taken.\*  
Berm area affected. Will sample when conditions improve

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Bobby Spearman	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: <b>2/1/2016</b>	Expiration Date:
E-mail Address: Robert.E.Spearman@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2/1/2016 Phone: (505) 320-3045	<b>Sample for BTEX, TPH, Chlorides</b> <b>NUF 1603939780</b>	

\* Attach Additional Sheets If Necessary

①