

FEB 08 2016

Form C-103

Revised November 3, 2011

Submit One Copy To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 811 S. First St., Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

WELL API NO.

30-045-21147

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
Candelaria Gas Com

8. Well Number 1

9. OGRID Number

000778

10. Pool name or Wildcat

Aztec Pictured Cliffs

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: ☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

BP America Production Company

3. Address of Operator

737 North Eldridge Parkway, 12.181A, Houston TX 77079

4. Well Location

Unit Letter K : 1730 feet from the South line and 625 feet from the West lineSection 18 Township 29N Range 09W NMPM _____ County San Juan11. Elevation (Show whether DR, RKB, RT, GR, etc.)
5552'

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐ CHANGE PLANS ☐PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐ P AND A ☐CASING/CEMENT JOB ☐☒ Location is ready for OCD inspection after P&A☒ All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.☐ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.☒ A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the

OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.

☐ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. Recontouring of location is not possible as Energen continues to use the entire pad for continued operations and has requested the entire pad be left for their operational area. BP equipment, junk, trash, and lines were stripped from location on 7/16/2014.

☒ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.

☐ If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.

☒ All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.) All BP items were removed from the location on 7/16/2014

☒ All other environmental concerns have been addressed as per OCD rules.

☒ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.

☐ If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure. Energen continues to utilize the cathodic protection on location and the power pole was left for landowner and Energen use.

When all work has been completed, return this form to the appropriate District office to schedule an inspection.

To schedule an inspection please contact Sabre Beebe at 970-375-7530 or sabre.beebe@bp.com

SIGNATURE Toya Colvin TITLE Regulatory Analyst DATE 02/04/2016TYPE OR PRINT NAME Toya Colvin E-MAIL: Toya.Colvin@bp.com PHONE: 281-366-7148

For State Use Only

APPROVED BY: Paul Wiebe TITLE DEPUTY OIL & GAS INSPECTOR DATE 2/26/2016

DISTRICT #3

N
2

Candelaria GC 001 is a shared location with Energen #18-2 Santa Rosa. Energen requested the entire pad including cathodic protection on site for their continued operations.

