



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-18-13 Operator Conrad Hill, PS API #30-0 39-23037

Property Name Lindeth Blvd Well No. 23 Location: Unit 16 Section 16 Township 24 Range 3

Well Status (Shut-In or Producing) Initial PSI: Tubing 63 Intermediate 274 Casing 379 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			
	Bradenhead		INTERM	
	BH	Int	Csg	Int
TIME				
5 min		<u>30</u>	<u>379</u>	<u>0</u>
10 min		<u>0</u>	<u>379</u>	<u>0</u>
15 min		<u>0</u>	<u>379</u>	<u>0</u>
20 min				
25 min				
30 min				

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges	<u>No Bradenhead</u>	
Down to Nothing	<u>4/2</u>	<u>/</u>
Nothing		
Gas	<u>KA</u>	<u>DIST. 3</u>
Gas & Water		<u>OIL CONS. DIV.</u>
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD No BH

INTERMEDIATE 274

REMARKS:

BH dead to nothing in 3 seconds

No Bradenhead Valve -

By Bruce Ambrose

Witness Monica Kuehling

- tested when fixed -

(Position)

E-mail address \_\_\_\_\_

RCVD APR 18 '13