



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

APR 12 2016

(submit 1 copy to above address)

Date of Test 4-12-16 Operator Durlington K API #30-0 39-30388
Property Name Johnston A Com C Well No. 9N Location: Unit E Section 36 Township 27 Range 6
Well Status (Shut-In or Producing) Initial PSI: Tubing 116 Intermediate 2 Casing 116 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	2	122	0	126
10 min	0	2	123	0	126
15 min	0	2	121	0	127
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	☒
Nothing	
Gas	☒
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

3H Long puff to clear in 2 seconds. Nothing
when opened after 5 min shut in. Int: Med blow
light at 1.44 to 2.44 - clear at 2 min. Nothing
when opened after 5 min shut in

By

Witness

(Position)

E-mail address _____