

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

FEB 24 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ConocoPhillips Company	Contact Lisa Hunter
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 258-1607
Facility Name: San Juan 28-7 Unit 165	Facility Type: Gas Well
Surface Owner State	Mineral Owner State (E-2825-6)
API No. 3003920518	

LOCATION OF RELEASE

Unit Letter A	Section 16	Township 27N	Range 07W	Feet from the 1040	North/South Line North	Feet from the 1180	East/West Line East	County Rio Arriba
-------------------------	----------------------	------------------------	---------------------	------------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------------


Latitude **36.578115** Longitude **-107.57441**

NATURE OF RELEASE


Type of Release Produced Water	Volume of Release 11bbl	Volume Recovered 3bbl
Source of Release Pit Tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 02/16/16 @ 8:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* During routine maintenance visit leak was discovered at bottom of pit tank. Truck was called to recover standing fluid (3bbbls).		
Describe Area Affected and Cleanup Action Taken.* ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature:



Approved by Environmental Specialist:


Printed Name: **Lisa Hunter**Title: **Field Environmental Specialist**Approval Date: **4/14/16**

Expiration Date:

E-mail Address: **Lisa.Hunter@cop.com**

Conditions of Approval:

Attached ☐Date: **February 22, 2016** Phone: **(505) 258-1607**

Test for TPH, BTEX, chlorides

* Attach Additional Sheets If Necessary

#NCS 16105 42560

If BGT pre 2008 must be Retorted or closed.

①